



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1140/2022/EQ
DATE : 20-Dec-22
WIP : 55538

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS WANG HUIMIN BETHANY
ADDRESS : 186A RIVERVALE DRIVE
#01-824
SINGAPORE 541186
TELEPHONE : HP +65 87401080
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220086642
VEHICLE NO : **SNG 3856 A**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 29/7/2022
ENGINE NO : DEM 032134
CHASSIS NO : WAUZZZF47MA065811
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Dec-22
PLACE OF ACCIDENT : TPE, SINGAPORE

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNG 3856 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	✓
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1750 (250) → 2000 S 3,500.00	S 200 + 1250 S.S.
6	TO RESPRAY FRONT BUMPER.	S 900.00	550 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,022.00	

* Additional 3 working days.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 3856 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 393.00	X
3	FRONT BUMPER SECURING STRIP - LH / RH <i>2 nh</i>	2	\$ 79.00	? X
4	FRONT BUMPER GRILLE - CENTER <i>could</i>	1	\$ 219.00	✓ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>could</i>	1	\$ 293.00	✓ 734.00
6	FRONT BUMPER AIR GUIDE - LH <i>Missing</i>	1	\$ 51.00	✓ 40.08
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	1	\$ 293.00	X
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	1	\$ 151.00	✓ 120.40
9	FRONT BUMPER OUTER GRILLE HOLE COVER - LH <i>missing</i>	1	\$ 54.00	✓ 42.64
10	RADIATOR GRILLE <i>could</i>	1	\$ 1,754.00	✓ 1403.20
11	FRONT BUMPER FOAM FILLER PIECE <i>2 nh</i>	1	\$ 212.00	? X
12	FRONT BUMPER REINFORCEMENT BEAM <i>2 nh</i>	1	\$ 899.00	? X
13	FRONT BUMPER BRACKET - LH <i>? nh</i>	1	\$ 254.00	? X
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 41.00	+
15	FRONT BUMPER TOP COVER	1	\$ 143.00	+
16	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	+
17	AIR CONDITIONER STICKER	1	\$ 9.00	X
18	FRONT BUMPER BRACKET <i>? nh</i>	1	\$ 154.00	? X
19	FRONT BUMPER SUPPORT - LH / RH <i>? nh</i>	2	\$ 64.00	? X
20	HORN HIGH TONE - LH <i>new</i>	1	\$ 134.00	X
SUB TOTAL SPARE PARTS			\$ 7,590.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Facebook

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 3856 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH <i>new</i>	1	\$ 33.00	+
22	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 532.00	+
23	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 10.00	+
24	FRONT BUMPER WIRING SET	1	\$ 642.00	+
25	HEADLIGHT - LH <i>new</i>	1	\$ 8,172.00	+
26	LIFT CYLINDER - LH <i>new</i>	1	\$ 231.00	+
27	LIFT CYLINDER BRACKET <i>new</i>	1	\$ 7.00	+
28	LIFT CYLINDER CORRUGATED PIPE <i>Dented</i>	1	\$ 107.00	✓ 88.80
29	LOCK CARRIER <i>cracked</i>	1	\$ 1,478.00	✓ 1,055.70
30	LOCK CARRIER SUPPORT <i>dented</i>	1	\$ 43.00	✓ 43.00 88.80
31	CHARGE AIR COOLER <i>Dented</i>	1	\$ 654.00	✓ 522.80
32	CHARGE AIR COOLER PRESSURE PIPE - LH <i>new</i>	1	\$ 496.00	+
33	A/C CONDENSER <i>new</i>	1	\$ 683.00	? X
34	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 186.00	+
35	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 381.00	+
36	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 277.00	+
37	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	+
38	RADIATOR <i>Dented</i>	1	\$ 699.00	✓ 574.40
39	READY-MIX COOLANT <i>new</i>	6	\$ 297.00	✓ 760.16
40	RADIATOR AIR GUIDE - LH INNER <i>Dented</i>	1	\$ 51.00	✓ 29.84
SUB TOTAL SPARE PARTS			\$ 15,000.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 3856 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - LH OUTER <i>nn</i>	1	\$ 19.00	? X
42	RADIATOR AIR GUIDE - UPPER / LOWER <i>3 nn</i>	2	\$ 44.00	? X
43	FRONT NOISE INSULATION <i>torn</i>	1	\$ 640.00 546.00	? ✓ <i>sls</i>
44	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 256.00	+
45	FRONT WHEEL SPOILER - LH <i>new Canceled</i>	1	\$ 82.00 68.96	? ✓ <i>sls</i>
46	FRONT WHEEL SPOILER END PLATE - LH <i>new</i>	1	\$ 39.00	+
47	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓
48	SUNDRIES <i>? new</i>		\$ 400.00	? 35.92 ✓
TOTAL SPARE PARTS			\$ 24,130.00	
TOTAL LABOUR CHARGES			\$ 8,022.00	
GRAND TOTAL			\$ 32,152.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

Xiao Chu

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1140/2022/EQ 17-Jan-23 CHANG 1 of 1 SNG 3856 A AUDI A4 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO DISMANTLE AND RENEW LH FRONT WISHBONE LINK. S/N	\$ 280.00	<i>✓</i>
Parts			
1	FRONT WISHBONE LINK - LH <i>lit</i> 1	\$ 605.00	<i>✓ 483.60</i>
GRAND TOTAL		\$ 885.00	

For Premium Automobiles Pte Ltd



Authorized Signature

Adrian Ling
Resumeyee!
 Add 3 days for the
 Replenishment of the lock
 carrier.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *21/12/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT