



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                                  |   |            |
|--|----------------------------------|---|------------|
| LIBERTY INSURANCE PTE LTD<br>51 CLUB STREET, #03-00<br>LIBERTY HOUSESINGAPORE 069428   |                                  | Ref: CS/LIP22012804/Twy3m4<br>Date: 03/02/2023<br>Code: LIP |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)   |                                  |   |            |
| Insured Veh.   | SJL 1487R                        | Veh. Inspected  | PC 5493Y   |
| Policy No.   |                                  | Coverage (\$)   | 0.00       |
| Claim No.  | BVS22/0988                       | Excess (\$)   | 0.00       |
| Assign From  | ESTHER CHEAH                     | Assign Date   | 21/12/2022 |
| 2. Vehicle Particulars & Condition   |                                  |   |            |
| Make & Model   | TOYOTA REGIUS                    | c.c   | 2982       |
| Engine No.   | HIDDEN                           | Year of Reg.  |            |
| Chassis No.  | KDH2010209067                    | Colour  | WHITE      |
| Odometer   | -                                | Steering  | IN ORDER   |
| Brakes   | IN ORDER                         | Modification  | NIL        |
| General  | GOOD                             |   |            |
| 3. Conditions of Tyres   |                                  |   |            |
|  | Size                             | Make  | Balance    |
| R/H Front Tyre   | 195/R15                          | MAXMILER  | 6 mm       |
| L/H Front Tyre   | 195/R15                          | MAXMILER  | 6 mm       |
| R/H Rear Tyre  | 195/R15                          | MAXMILER  | 6 mm       |
| L/H Rear Tyre  | 195/R15                          | MAXMILER  | 6 mm       |
| 4. Description of Damages  |                                  |   |            |
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.<br>REPAIR CONDITION SEE DETAILS.   |                                  |   |            |
| 5. General Information   |                                  |   |            |
| Accident Date  | 20/08/2022                       | Inspection Date   | 23/12/2022 |
| Survey held at   | 4 PENJURU CLOSE SINGAPORE 608574 |   |            |
| Repairer   | AAK LOGISTICS SERVICES PL        |   |            |
| 5a. Remarks  |                                  |   |            |
| A)REGISTRATION DATE: 04 JAN 2017<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                  |   |            |
| 5b. Estimate Days of Repair  |                                  |   |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |                                  | 20 Working Days   |            |