



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKU8048U Porsche Cayenne V6 TIPTRONIC

WP12229YZLDA0 2517

TP China

Veron

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>shame 2pin</i>	\$ 3,857.15*
2	1	Bumer side bracket <i>And 2</i>	\$ 600.00 300.
3	1	Rear reinforcement <i>xre m</i>	\$ 3,190.00 x
4	1	Tow cover <i>xre m</i>	\$ 150.00 x
5	1	Lower lip upper Matt black <i>lit</i>	\$ 2,865.15 1220
6	1	Lower lip lower Matt black <i>xre m</i>	\$ 2,690.00 x
7	1	Porsche logo <i>3re m</i>	\$ 380.00 x
8	1	Cayenne logo	\$ 220.00 x
9	1	Rear ruber strip <i>3re m</i>	\$ 495.80 x
10	2	Rear bumper sensor left side	\$ 900.00 x
11	2	Exhaust heat shield <i>3re m</i>	\$ 800.00 x
12	1	Exhaust cover left	\$ 500.00 x
13	1	Bumper cabel holder -single use one set <i>new</i>	\$ 180.00 ✓
14	2	Wheel housing trim linning 2 joint piece <i>new</i>	\$ 950.00 500.
Parts sub-total			\$ 17,778.10

3420

Len 10% : 3078



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKU8048U Porsche Cayenne V6 TIPTRONIC

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>new</i>	\$ 120.00 50.
2	12	Rear bumper side cover clips <i>new</i>	\$ 80.00 x
3	6	Rear lower lip upper garnish clips <i>new</i>	\$ 100.00 50
4	8	Rear lower lip lower garnish clips <i>new</i>	\$ 120.00 x
7	12	Wheel housing trim clips <i>new</i>	\$ 60.00 30
11	1	Rear no plate with casing <i>new</i>	\$ 100.00 x
Total specail nett item			\$ 580.00

150



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKU8048U Porsche Cayenne V6 TIPTRONIC

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, including rear end panel	\$ 2,500.00 350.
2	To putty and spray painting damaged area	\$ 2,500.00 350.
3	To apply anti rust proofing to front affected area.	\$ 250.00 x.
4	To check rear lighting and wiring.	\$ 120.00 30
5	To remove and install rear bumper reverse sensor.	\$ 150.00 60
6	To conduct wheel alignment-rear left	\$ 150.00 x.
7	Ceremic coating for rear	\$ 600.00 300.
8	Water test after repair	\$ 120.00 x
9	Remove both fender internal trim to facilitate this repair	\$ 250.00 x.
10	Re-programming and re-set system, remove accident fault code	\$ 300.00 150.
Total labour :		\$ <u>6,940.00</u>

total: 4468

L/S: 3.5K. ✓

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: