

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 439180
FAX. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 64465
Date Estimated : 22/12/2022
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Soh Sim Karn
235 Tembeling Rd
#04-03

Singapore 423720

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW4590L	WBA6V120705N97663	21/11/2019	216i Gran Tourer	26680

DESCRIPTION

To replace front bumper, support left, reinforcements, attachments and make good of bonnet and front left door.

2550 1700 5,100.00

To painting front bumper, fender left, bonnet and front left door.

2668 1972 4,412.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

✓ 168 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

✓ 168 177.00

To replace left or right headlight.

✓ AS7 481.00

To carry out body cavity preservation. (Per panel).

✓ 112 118.00

Sundries.

✓ ? 150.00

Total Labour 1: 10,615.00

DESCRIPTION

FRT LH FENDER
LH EXTENSION WHEEL HOUSING STRUT
LH CROSS SUPPORT SIDE PANEL
LH FOG LAMP SUPPORT
LH MOULDING (LUXURY)
LH FINISHER
FRT BUMPER PRIMED PANEL (PMA)
LH GRID LATERAL (LINES/PDC)
GROMMET
LH SUPPORT HEADLIGHT ARM
FRT LH WHEEL ARCH COVER
LH AIR DUCT DISPLACED RADIATOR
PLAQUE 82MM

QTY	PRIC	VALUE
1	639.70	639.70
1	173.00	173.00
1	33.10	33.10
1	80.55	80.55
1	69.15	69.15
1	53.30	53.30
1	950.80	950.80
1	96.95	96.95
2	0.80	1.60
1	78.50	78.50
1	138.40	138.40
1	72.65	72.65
1	72.85	72.85

bt 639.70 ✓
bt 173.00 ✓
nn 33.10 X
nn 80.55 X
nn 69.15 ✓
at 53.30 ✓
de 950.80 ✓
cut 96.95 ✓
nel 1.60 X nn
de 78.50 ✓
X nn 138.40 X
L 72.65 X
nu 72.85

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64795601 (AfterSales)
 64795624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 64465
 Date Estimated : 22/12/2022
 Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW4590L	WBA6V120705N97663	21/11/2019	216i Gran Tourer	26680

Total Parts : 2,460.55

Taufik 9745749
Not advise Rent
22/12/22 @ 1145
Ex: \$500
Using before paint
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

20,760.10



Labour 1	:	10,615.00
Parts	:	2,460.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	915.29
Grand Total	:	13,990.84

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 64465
Date Estimated : 22/12/2022
Prepared By : Inthiran A/L Thurasamy

Page No. :

- ESTIMATE REPAIR FOR -

Soh Sim Karn
235 Tembeling Rd
#04-03

Singapore 423720

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMW4590L	WBA6V120705N97663	21/11/2019	216i Gran Tourer	29536

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front bumper and attachments, front LH fender and attachments, LH extension wheel housing strut, LH headlight arm support include making good the front LH door and knocking out dents caused by the accident	2,550.00	0.00	2,550.00

* To spray paint front bumper, front LH fender and front LH door	2,668.00	0.00	2,668.00
--	----------	------	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER LH INSERT	14.20	1.00	0.00	14.20 <i>de</i>
# FRT LH SIDE PANEL TOP MOUNTING	18.90	1.00	0.00	18.90 <i>de</i>
# EXPANDING RIVET	0.45	4.00	0.00	1.80 <i>not</i>
# FRT LH FENDER SEALING	34.55	1.00	0.00	34.55 <i>not</i>
# LH HEADLIGHT LED TECHNOLOGY	2,399.10	1.00	0.00	2,399.10 <i>Chris</i>

SUPPLEMENTARY ITEMS

Total Labour :	5,218.00
Total Parts :	2,468.55
Total Labour & Parts (before GST) :	7,686.55

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

