

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP China.
Xiao Chen.

ESTIMATE

Vehicle No : SLX 585 K
Chassis No: GK81200885

Make/Model : HONDA SHUTTLE
Accident date : 20.12.2022

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front bumper <i>Rehead</i>	1	\$ 1,260.00 <i>985</i>
2	Front bumper side holder @ \$24.00 <i>new</i>	2	\$ 48.00 <i>x.</i>
3	Front bumper reinforcement <i>new</i>	1	\$ 356.40 <i>x.</i>
4	Front grille <i>cracked.</i>	1	\$ 474.00 <i>363</i>
5	Front grille "H" emblem <i>new</i>	1	\$ 32.00 <i>✓</i>
6	Front headlamp @ \$2,700.00 <i>RH cracked.</i>	2	\$ 5,400.00 <i>2150.</i>
7	Front support panel <i>new</i>	1	\$ 942.00 <i>+</i>
			\$ 8,512.40
		Less 20% Disc	\$ 1,702.48
		Total	\$ 6,809.92
Special Nett Items			
1	Front number plate <i>ht</i>	1	\$ 50.00 <i>30</i>
2	Front number plate holder <i>ht</i>	1	\$ 50.00 <i>30</i>
3	Front grille clips (1 set) <i>new</i>	1	\$ 60.00 <i>20</i>
4	Front bumper clips (1 set) <i>new</i>	1	\$ 60.00 <i>30</i>
		Total	\$ 220.00
Labour Cost			
1	Remove & reinstall air con fill in gas		\$ 150.00 <i>+</i>
2	Remove ,replace & repair consistent to the accident	<i>500</i>	\$ 1,100.00 <i>300</i>
3	Respray painting		\$ 1,000.00 <i>200.</i>
		Total	\$ 2,250.00
		Grand Total	\$ 9,279.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3434
2/s: 2.7k. ✓
03 Days.