

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 10 Feb 2023

Preliminary Advice

Insured Vehicle No	: SLX2296G	Accident Date	: 20/12/2022
TP Vehicle No	: SLX585K	Assignment Date	: 22/12/2022
Make	: HONDA SHUTTLE	Est. Duration of Repair	: 3
Date of Inspection	: 28/12/2022		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,279.92
Revised Amount	:S\$	3,434.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,434.00

Lump Sum Repair	:S\$	2,700.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.