

CS/CTI 22012814/RVY3
Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

21 DEC 2022

Estimate No. : b1 64408
 Date Estimated : 19/12/2022
 Prepared By : Yap Mee Key

Page No. : 1 of 5

ESTIMATE REPAIR FOR -

- ACCOUNT - 40000

Cash Sales - Service
 Singapore

Jian Wei
 Hong San Walk
 -03

Singapore 689051

N. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
9799M	WBA6V120805T50443	24/06/2021	216i Gran Tourer	20642

DESCRIPTION

VALUE

To replace rear bumper and make good tailgate.

✓ 1700 2,125.00

To respray rear bumper and tailgate.

✓ 1826 1,923.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

✓ 168 177.00

To check electrical.

✓ 168 177.00

To carry out body cavity preservation.1x
 (Per panel).

X 118.00

Sundries.

80 40.00

Total Labour 1: 4,560.00

DESCRIPTION

QTY

PRIC

VALUE

C CLIP FOR PLASTIC NUT *an* / *X an*

2 1.10

2.20

C-clip *an* / *X an*

2 1.70

3.40

REAR BUMPER CARRIER ? *X an*

1 490.70

490.70

SUPPORT ? *X an*

1 47.00

47.00

PLUG IN NUT *an* / *X an*

2 3.10

6.20

REAR BUMPER TRIM STRIP (BLACK) *SCA* /

1 75.80

75.80

REAR BUMPER PANEL PRIMED (LINES PDC) *de* /

1 1,088.30

1,088.30

Total Parts : 1,713.60

303, Alexandra Road
Simme Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Simme Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 64408
Date Estimated : 19/12/2022
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ9799M	WBA6V120805T50443	24/06/2021	216i Gran Tourer	20642

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement
Regn No. _____ Claim No. _____
Date&Time 11/01/23 @ 1030 Excess S\$ _____
Surveyor's Name Ramee Sign _____
Surveyor's Tel 90000068 A. Unused Yes / No _____
Insured Date _____ Time _____
Insured YES OR Yes / No PML Yes / No _____
Surveyor's Days Recommend 4 days



6313.60

Labour 1	:	4,560.00
Parts	:	1,713.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	439.15
Grand Total	:	6,712.75

* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**