

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 08 Feb 2023

Preliminary Advice

Insured Vehicle No	: SKQ5974L	Accident Date	: 21/12/2022
TP Vehicle No	: SLT2346S	Assignment Date	: 23/12/2022
Make	: HONDA VEZEL	Est. Duration of Repair	: 5
Date of Inspection	: 28/12/2022		
Inspection At	: A T AUTO CONSULTANT (HQ) B/113 TECK WHYE LANE, #05-650 SINGAPORE 680113		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,088.80
Revised Amount	:S\$	3,550.60
Check Items (Estimated)	:S\$	2,440.80
Total	:S\$	5,991.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- The vehicle is economical for repair
- The vehicle is not economical for repair
- Part-by-Part repair
- Lump Sum repair

- The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.