

ASS. REC. BY:

REF:

MSG-1 22012816/K9Y3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 871K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 23465 Yr Regn: 10, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vireo c.c. 1496Colour: Ar. Red A/C: Insured / Std / NI / NASp. Reading: 121100 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: R41 1223502Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 21/12/22

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 28/12/2022Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/3 11:00 @ 32506 Carv cred 88852.20, 73%

re-adjusted the repair cost at LS \$3200 due to amend the tailgate lock price to \$250.50.
(Red \$8852.20, 73%)

Date/Time, File Pass to?

☐ : Prell. Report

1) 04/05 Typist

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$) 3200 2250

TOTAL

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com

Co. Reg. No. : 53368526E

Date of Estimate: 22.12.2022

Vehicle No: SLT2346S

Owner: YEO HWEE LIAN SOPHIA

Date of Accident: 21.12.2022

Make & Model: Honda Vezel

Chassis No : RU11223502

ESTIMATE FOR ACCIDENT VEHICLE NO SLT2346S

PARTS

1	1	Rear bumper	366
2	2	Rear corner panel LH/RH	
3	2	Rear bumper side retainer LH/RH	
4	2	Rear bumper reflector LH/RH	
5	1	Tailgate	953.
6	1	Tailgate reflector LH/RH	
7	1	Tailgate lock	
8	1	Tailgate inner trim	250.50
9	1	Tailgate windscreen seal	P-7 112.20
10	1	Tailgate weatherstrip	298
11	1	Tailgate emblem "VEZEL"	
12	1	Tailgate moulding	
13	1	Taillamp LH/RH	
14	1	Taillamp corner panel LH/RH	
15	1	Rear end panel	411.90
16	1	Rear end panel top garnish	180.90
17	1	Rear floor panel	
18	1	Rear floor panel top garnish	
19	1	Rear floor panel under cover	
20	1	Rear tool box garnish	
21	1	Remote key buzzer	

SUB TOTAL

LESS 20 %

DISCOUNTED SUB TOTAL

Buc/No	\$1,100.00	✓
@	\$298.00	Pr \$596.00 X
@	\$59.00	Pr \$118.00 X
@	\$151.00	Pr \$302.00 X
		Pr \$1,386.00 ✓
@	\$412.00	Pr \$824.00 X
		Pr \$339.00 ✓
		Pr \$301.00 ✓
		Pr \$385.00 ✓
		Pr \$321.00 508.1m
		Pr \$72.00 ✓
		Pr \$422.00 X
@	\$467.00	Pr \$934.00 X
@	\$281.00	Pr \$562.00 X
		Pr \$556.00 ✓
		Pr \$286.00 ✓
		Pr \$912.00 X
		Pr \$378.00 X
		Pr \$365.00 X
		Pr \$265.00 X
		Pr \$87.00 ✓
	\$10,511.00	
	\$2,138.80	
	\$8,372.20	

S. NETT ITEM

1	1set	Rear bumper clips
2	1set	Reverse sensor
3	1set	Rear number plate & garnish
4	1	Reverse cam

SUB TOTAL

LESS 0 %

DISCOUNTED SUB TOTAL

Pr	\$50.00	✓
Pr	\$330.00	200m
Pr	\$100.00	X
Pr	\$180.00	X
	\$660.00	
	\$0.00	
	\$660.00	

LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges
4	Apply undercoating to above affected areas
5	Remove/refix reverse sensor
6	Remove/refix tailgate components
7	Remove/refix tailgate windscreen

SUB TOTAL (LABOUR)

Page 1 of Acknowledged by Repairer

Signature:

Date:

AT Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$1,200.00	600
\$1,200.00	400
\$100.00	150
\$120.00	300
\$50.00	✓
\$100.00	600
\$250.00	1200
\$3,020.00	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	754I
Vehicle Details	
Vehicle No.:	SLT23465
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Dec 2022
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	L15B4423504
Chassis No.:	RU11223502
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,487.00
Original Registration Date:	23 Oct 2017
First Registration Date:	23 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$13,482.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2027
PARF Rebate Amount:	\$9,437.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$17,343.00
Total Rebate Amount:	\$26,780.00

The information contained herein is correct as at 27 Dec 2022

OK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts photos are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company