

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 03 Feb 2023

Preliminary Advice

Vehicle No	: YQ754Y	Accident Date	: 08/12/2022
Make	: ISUZU NNR85UH4A	Policy No.	: DMCVSNW00066032200
Assignment Date	: 23/12/2022	Excess	: S\$550.00
Date of Inspection	: 23/12/2022	Est. Duration of Repair	: 14 days
Inspection At	: AUTO INSURE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,895.12
Revised Amount	:S\$	13,530.12
Check Items (Estimated)	:S\$	10,365.00
Total	:S\$	23,895.12
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	17,146.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,854.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle recommends Total Loss as the chassis was found damaged.