

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22012819/UNY3Q2**Date:** 03/02/2023**REFERENCE**

Insured/Claimant: TAN SUM CHYE Policy No: DMPCSNW00172962200

Date of Loss: 20/12/2022 Nature of Claim: OD Claim No: SNM22D209180/C01/CHNGPW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SDT1991E**  
 Make & Model: MAZDA 3, 2.0 SEDAN SPORTS EU6 (A) Engine No: PE20918619  
 Reg. Date: 18/07/2017 (Man. Year: 2017) Chassis No: JM6BN2278H0156580  
 Colour: Black/White Odometer: 57045 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: S\$69,000.00  
 Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/55Z R19 Rear Tyre Size: 245/55Z R19  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,980.00	8,614.00	366.00	4.08
Miscellaneous Items	135.00	100.00	35.00	25.93
Labour	679.69	651.97	27.72	4.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,794.69</b>	<b>9,365.97</b>	<b>428.72</b>	<b>4.38</b>
<b>- Excess (\$\$)</b>	0.00	1,000.00	-1,000.00	
<b>(\$\$)</b>	9,794.69	8,365.97	1,428.72	14.59
<b>+ GST 7.00/7.00% (\$\$)</b>	685.63	585.62	100.01	14.59
<b>Nett Amount (\$\$)</b>	<b>10,480.32</b>	<b>8,951.59</b>	<b>1,528.73</b>	<b>14.59</b>

**INSPECTION**

Date of Assignment: 23/12/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)  
 Date Inspected: 27/12/2022 Inspected At: Car City Auto Centre Pte Ltd (HQ)  
 Estimated Period of Repair: 4.0 days Blk 9006 #01-198, Tampines Street 93  
 Singapore 528840

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2023)
Parts:	143	MAZDA 3 2.0 SEDAN SPORTS EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDT1991E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		8,980.00 F	*8,614.00 F
F=Franchise part.						
				Total Parts (\$\$)	8,980.00	8,614.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRA	135.00	100.00
Sub Total (\$\$)			135.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	130.20	142.80
2	SPRAY PAINTING	New	549.49	509.17
Gross Labour Cost (\$\$)			679.69	651.97

Report was unsubmitted during this print-out.

< END OF ESTIMATES >