

ASSIGNMENT

From:

Date:

Veh No:

SD71991E

Yr Regn:

18/07/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SD71991E

at Workshop m/s

Car city

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

1000

(Client's Record)

Make of Veh:

Make:

Nagda 3

c.c 1998

Colour

white / black

A/C: Insured / Std / NI / NA

Sp. Reading

57045

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN227840156580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/55ZR19

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

469k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

1.3/

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

9637

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 38293

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/12/22

D.O.I.

27/12/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

wrap sticker

Rep 13k.

1/12/23 P/P 9365.97 in hand Anson (Red. \$428.72, 4%)

Date/Time, File Pass to?

☐

Preli. Report

1) 1/2/23

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

OD

Lump Sum / I.B.I: (\$

9365.97

)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 963J

Vehicle Details

Vehicle No.: SDT1991E

Vehicle to be Exported: No

Intended Deregistration Date: 27 Dec 2022

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 SEDAN SPORTS 2.0 AT EU6

Primary Colour: White

Manufacturing Year: 2017

Engine No.: PE20918619

Chassis No.: JM6BN2278H0156580

Maximum Power Output: 121.0 kW (162 bhp)

Open Market Value: \$20,626.00

Original Registration Date: 18 Jul 2017

First Registration Date: 18 Jul 2017

Transfer Count: 0

Actual ARF Paid: \$20,877.00 10438

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Jul 2027

PARF Rebate Amount: \$14,613.00

Intended COE Rebate Details

COE Expiry Date: 17 Jul 2027

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$52,000.00

COE Rebate Amount: \$23,680.00

Total Rebate Amount: \$38,293.00

The information contained herein is correct as at 27 Dec 2022

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement

Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2019 Facelifted Porsche Macan S 3.0A PDK For Sale!



Lower Depre Than 2016/17/18!
5 Years Stuttgart Warranty &
Free Maintenance!
Seng Hup Auto StarAd

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

« Back (1 2 3 4 5) Next »

Sort by 20 results/page

82 vehicles



Mazda 3

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 3		Any	Any	2017	Any	Any	Any	Available
	Mazda 3 1.5A		\$56,800	\$12,080 /yr	17-Apr-2017	1,496 cc	61,000 km	Sedan	Available
Well maintained unit, well kept by previous owner, bank/in-house loan available, full loan available, trade-in welcome, hassel free and fa...									
☞ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More									
Posted: 16-Dec-2022									
	Mazda 3 1.5A Sunroof		\$62,988	\$11,720 /yr	07-Dec-2017	1,496 cc	85,800 km	Sedan	Available
Free Servicing Available. SGCM Premium Dealer. Accident Free. Full Loan! \$0 Downpayment/low Interest Rate/flexible Loan Scheme Wit...									
Carz World Pte Ltd									
Posted: 27-Dec-2022									
	Mazda 3 1.5A Sunroof		\$59,800	\$11,520 /yr	27-Sep-2017	1,496 cc	87,578 km	Sedan	Available
2 Owners, 1 Year Extended Warranty By Sgcarmart Premium Dealer With Official Warranty Certificate, Low Mileages, High Loan Availabl...									
☞ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More									
CARWAY									
Posted: 27-Dec-2022									
	Mazda 3 1.5A Sunroof		\$58,800	\$12,540 /yr	17-Apr-2017	1,496 cc	88,000 km	Sedan	Available
Most Popular Mazda Sedan! Road Tax Till Apr 23, Regular Servicing Done, Low Maintenance Cost, Spacious Cabin And Boot, Smooth Dri...									
Posted: 27-Dec-2022									
	2022 Mazda 3 Mild Hybrid 1.5A (For Lease)								
\$2,250/mth Brand New Unit - Mazda 3 1.5A (2022) Sedan Mild Hybrid available for lease. Contact us @ 97867033/80281096 for more info									
More info about this vehicle									
	Mazda 3 1.5A Sunroof		\$62,800	\$11,790 /yr	23-Nov-2017	1,496 cc	79,000 km	Sedan	Available
100% non PHV, no accident, no repair needed. Low Mileage, Well Maintained By The Owner.									
Posted: 27-Dec-2022									
	Mazda 3 1.5A Sunroof		\$61,800	\$13,070 /yr	09-May-2017	1,496 cc	92,000 km	Sedan	Available
Just arrived! Well maintained by previous owner! Loan with high trade in available. Price negotiable. Call now or visit our showroom today.									
Posted: 27-Dec-2022									
	Mazda 3 1.5A Deluxe		\$67,500	\$12,720 /yr	25-Sep-2017	1,496 cc	99,000 km	Sedan	Available
You will never find another mazda 3 deluxe like this in the market! fully black out 3M wrap that almost costing \$3,000! this whole unit fe...									
Posted: 26-Dec-2022									

Compare

Car City Auto Centre Pte Ltd
#01-198, Blk 9006 Tampines Street
93,
528840

Insurer Reference: SDT1991E
Repairer Reference: OD/22078
Date calculated: 23/12/2022 10:15 AM

Full Report
Registration: SDT1991E
Printed: 23/12/2022 10:15 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Anson Seah	Currency:	SGD
Claim Reference:	SDT1991E	Date of Incident:	20/12/22
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: MAZDA
Model: 3 (BM/BN)
Sub Model: AMBITION
Model Sheet Number: 36 68 03
Registration: SDT1991E
VIN number:
Odometer: 56959

Model Specs

FROM 01.2017	2 ZONE AIR CON	BI-XENON HEADLAMPS	I-ELOOP SYSTEM
ANTI-THEFT ALARM	ULTRASONIC PARK SYS	2.0 LTR 121KW	CRUISE CONTROL
4-DOOR SALOON	RAD GRILLE BLACK	TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD			

*Not Authorized
for*

Survey?

27/12/22

Telephone before painting

4 days

1/1/23

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	----------------------------	---------------------------	---------------------------	----------------------------	----------------------------	-----------------------------	-----------

Fair

Fair

Spare Tyre Brand Tread (Spare), mm

5

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
S0201C-R-X	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		7.0	29.40
S0204A-R-X)	RENEW RADIATOR GRILLE		5.0	21.00
T0301A-R-X)	R + R L/F HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
T0301A-R-X)	R + R R/F HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
S0612G-R-X)	R + R FRONT PANEL		12.0	50.40
S0503X-R-X	RENEW BONNET		5.0	21.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	3.10	31.0	130.20
Total of Labour			130.20

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/hy
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	26.0
	LOCK CARR CTR SUPP SURFACE PAINT	5.0
	FRONT BUMPER NEW PART PAINT K1R	11.0
	TOWING EYE COVER NEW PART PAINT K1R	3.0
	FRT BUMPER GRILLE NEW PART PAINT K1R	5.0
	R/INNER SENSOR COVER NEW PART PAINT K1R	3.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	87.20
1019	LOCK CARR CTR SUPP SURFACE PAINT	6.23
0281	FRONT BUMPER NEW PART PAINT K1R	52.64
0321	TOWING EYE COVER NEW PART PAINT K1R	0.49
0349	FRT BUMPER GRILLE NEW PART PAINT K1R	14.76
0372	R/INNER SENSOR COVER NEW PART PAINT K1R	1.97

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		53.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	83.0	348.60

Material Cost - Paint

	Price SGD
New Part Painting	87.20
New Part Painting - Plastic K1R	69.86
Surface-/Blend Paint	6.23
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	200.89

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0281	FRONT BUMPER	BHS350031B8N	Original	Bin ✓	450.00
0283	L/BUMPER BRACKET	BHN1500U1E	Original	11 X	20.00
0284	R/BUMPER BRACKET	BHN1500T1F	Original	11 X	20.00
0287	L/LWR BUMPER BRACKET	BANE50163	Original	Che ✓	20.00
0288	R/LWR BUMPER BRACKET	BANE50153	Original	Che ✓	20.00

Code	Description	Part Number	Part Source	Price SGD
0321	TOWING EYE COVER	B63B50A11BB	Original 11 X	15.00X
0323	UPP RAD GRILLE COVER	BANE50033A51	Original cr	-200.00
0340	FRT BUMPER SUPPORT	BJS750070C	Original R X	350.00X
0345	FRT BUMP GRILLE BRKT	BHN1501A1C	Original su X	30.00X
0349	FRT BUMPER GRILLE	BJE450712B	Original su	100.00
0354	FRT CTR BUMPER MLDG	B45D50712A	Original su	300.00
0358	R/F INNER SENSOR	BHR167UC1	Original cr	-120.00
0369	L/F BUMPER MOULDING	B63B507K1A	Original cr	-120.00
0370	R/F BUMPER MOULDING	B63B507J1A	Original cr	-120.00
0372	R/INNER SENSOR COVER	BHR167UC5	Original dec 20	-120.00
0433	MANUFACTURER BADGE	D10J51730	Original MIS	-50.00
0471	BONNET	BHY05231XA	Original su	-850.00
0561	L/F HEADLAMP	BHT551041A	Original cr	-2,700.00
0562	R/F HEADLAMP	BHT551031A	Original cr	-2,700.00
1009	FRONT PANEL	BPN253110	Original sent	-300.00
1019	LOCK CARR CTR SUPP	B45A5215Y	Original su X	50.00X
1021	INN REAR PANEL TRIM	BHN9501C0A	Original 11 X	20.00X
1351	UPP INN FRONT PANEL	BHN1501C0B	Original su	-90.00
1355	UPPER FRONT PANEL	B45A53150	Original su	-80.00
1003	FRONT NUMBER PLATE	NUMBER PLATE	Original 11 X	35.00X
Savings				0.00
Subtotal				8,880.00
Fixed Sundry Parts Price				100.00
Total				8,980.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1000	ANTI-FREEZE 3 LITRE ANTI-FREEZE	11 60.00X
1001	AIR-CON GAS AIR-CON GAS	11 50.00X
1002	CHECK WIRING CHECKING WIRING	11 25.00X
Total Extras		135.00

8240

2-8814

Final Calculation

	SGD	SGD
Parts	8,880.00	
Fixed Sundry Parts Price	100.00	
Total Parts		8,980.00
Labour Time Base 10 WU/h		
Total 31.0 WU X 42.00 SGD/h	130.20	
Total of Labour		130.20
Total Of Extras		135.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Material Cost	200.89	
Total Paint Including Material		549.49
Repair Cost Excludes GST		9,794.69
GST (+7.0%)		685.63
Repair Cost Included GST		10,480.32

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Car City Auto Centre Pte Ltd
#01-198, Blk 9006 Tampines Street
93,
528840

Insurer Reference: SDT1991E
Repairer Reference: OD/22078
Date calculated: 31/12/2022 10:25 AM

Full Report
Registration: SDT1991E
Printed: 31/12/2022 10:25 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Anson Seah	Currency:	SGD
Claim Reference:	SDT1991E	Date of Incident:	20/12/22
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MAZDA
Model:	3 (BM/BN)
Sub Model:	AMBITION
Model Sheet Number:	36 68 03
Registration:	SDT1991E
VIN number:	
Odometer:	56959

Model Specs

FROM 01.2017	2 ZONE AIR CON	GRILLE TRIM CHROMED	BI-XENON HEADLAMPS
I-ELOOP SYSTEM	ANTI-THEFT ALARM	ULTRASONIC PARK SYS	2.0 LTR 121KW
CRUISE CONTROL	4-DOOR SALOON	RAD GRILLE BLACK	TWO COAT METALLIC
PREPARE OFF VEHICLE	CLEAR COAT HARD		

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Middle), mm						Condition
	mm	mm	mm	mm	mm	mm	
							Fair
							Fair

Spare Tyre Brand Tread (Spare), mm
5

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
S0201C-R-X	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		7.0	29.40
S0204A-R-X)	RENEW RADIATOR GRILLE		5.0	21.00
T0301A-R-X)	R + R L/F HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
T0301A-R-X)	R + R R/F HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
S0612G-R-X)	R + R FRONT PANEL		12.0	50.40
S0503X-R-X	RENEW BONNET		5.0	21.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	3.10	31.0	130.20
Total of Labour			130.20

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	26.0	
	LOCK CARR CTR SUPP SURFACE PAINT	5.0	
	FRONT BUMPER NEW PART PAINT K1R	11.0	
	TOWING EYE COVER NEW PART PAINT K1R	3.0	
	FRT BUMPER GRILLE NEW PART PAINT K1R	5.0	
	R/INNER SENSOR COVER NEW PART PAINT K1R	3.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	87.20
1019	LOCK CARR CTR SUPP SURFACE PAINT	6.23
0281	FRONT BUMPER NEW PART PAINT K1R	52.64
0321	TOWING EYE COVER NEW PART PAINT K1R	0.49
0349	FRT BUMPER GRILLE NEW PART PAINT K1R	14.76
0372	R/INNER SENSOR COVER NEW PART PAINT K1R	1.97

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			53.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	8.30	83.0	348.60

Material Cost - Paint

	Price SGD
New Part Painting	87.20
New Part Painting - Plastic K1R	69.86
Surface-/Blend Paint	6.23
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	200.89

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0260 ✓	FRT NO PLATE REINF	BHR150170	Supplementary	ADD	48.00 ✓
0281 ✓	FRONT BUMPER	BHS350031B8N	Original		450.00 ✓
0287 ✓	L/LWR BUMPER	BANE50163	Original		20.00 ✓
	BRACKET				
0288 ✓	R/LWR BUMPER	BANE50153	Original		20.00 ✓
	BRACKET				
0323 ✓	UPP RAD GRILLE COVER	BANE50033A51	Original		200.00 ✓

Code	Description	Part Number	Part Source	Price SGD
0349 ✓	FRT BUMPER GRILLE	BJE450712B	Original	100.00 ✓
0354 ✓	FRT CTR BUMPER MLDG	B45D50712A	Original	300.00 ✓
0358 ✓	R/F INNER SENSOR	BHR167UC1	Original	120.00 ✓
0369 ✓	L/F BUMPER MOULDING	B63B507K1A	Original	120.00 ✓
0370 ✓	R/F BUMPER MOULDING	B63B507J1A	Original	120.00 ✓
0372 ✓	R/INNER SENSOR COVER	BHR167UC5	Original	20.00 ✓
0381 ✓	L/UPP RAD GRILLE CVR	B63B50B51	Supplementary	28.00 ✓
0382 ✓	R/UPP RAD GRILLE CVR	B63B50B41	Supplementary	28.00 ✓
0383 ✓	L/GRILLE TRIM	B63C50B51	Supplementary	28.00 ✓
0384 ✓	R/GRILLE TRIM	B63C50B41	Supplementary	31.00 ✓
0385 ✓	L/F PANEL TRIM	B63D50B51	Supplementary	28.00 ✓
0386 ✓	R/F PANEL TRIM	B63D50B41	Supplementary	28.00 ✓
0387 ✓	UPPER GRILLE TRIM	B63B50B31	Supplementary	43.00 ✓
0388 ✓	CENTRE GRILLE TRIM	B63E50B31	Supplementary	43.00 ✓
0389 ✓	RADIATOR GRILLE TRIM	B63D50B31	Supplementary	43.00 ✓
0433 ✓	MANUFACTURER BADGE	D10J51730	Original	50.00 ✓
0471 ✓	BONNET	BHY05231XA	Original	850.00 ✓
0561 ✓	L/F HEADLAMP	BHT551041A	Original	2,700.00 ✓
0562 ✓	R/F HEADLAMP	BHT551031A	Original	2,700.00 ✓
1009 ✓	FRONT PANEL	BPN253110	Original	300.00 ✓
1351 ✓	UPP INN FRONT PANEL	BHN1501C0B	Original	90.00 ✓
1355 ✓	UPPER FRONT PANEL	B45A53150	Original	80.00 ✓
1003 ✓	L/F GRILLE MOULDING	B63E-50-B51B	Supplementary	13.00 ✓
1004 ✓	R/F GRILLE MOULDING	B63E-50-B41B	Supplementary	13.00 ✓
Savings				0.00
Subtotal				8,614.00
Fixed Sundry Parts Price				100.00
Total				8,714.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1000	ANTI-FREEZE 3 LITRE ANTI-FREEZE	60.00* X
1001	AIR-CON GAS AIR-CON GAS	50.00* X
1002	CHECK WIRING CHECKING WIRING	25.00* X
Total Extras		135.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	8,614.00	
Total Parts	100.00	8,714.00
Labour Time Base 10 WU/h		
Total 31.0 WU X 42.00 SGD/h	130.20	
Total of Labour		130.20
Total Of Extras		135.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Material Cost	200.89	
Total Paint Including Material		549.49
Repair Cost Excludes GST		9,528.69
GST (+7.0%)		667.0
Repair Cost Included GST		10,195.70

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.