

Performance Motors

BMW Dealer



Supplementary

Estimate No. : **b1 64457**
Date Estimated : **22/12/2022**
Prepared By : **Chua Kee Sin**

Page No. :

- ESTIMATE REPAIR FOR -

Lee Wen Chie (Li WenQi)
966 Dunearn Road
#05-08

Singapore 589488

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SNA4712G	WBA6V120505T62176	24/06/2021	216i Gran Tourer	31376

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace rear bumper and attachments, boot lid and attachments include knocking out dents caused by the accident	1,700.00	0.00	1,700.00
* To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	504.00	0.00	504.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT	1.05	4.00	0.00	4.20 ✓ nec
# BUMP STOP	3.45	10.00	0.00	34.50 ✓ nec

SUPPLEMENTARY ITEMS

Total Labour :	2,204.00
Total Parts :	38.70
Total Labour & Parts (before GST) :	2,242.70

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

