



Final Report

Estimate No. : **b1 64457**
 Date Estimated : **22/12/2022**
 Prepared By : **Chua Kee Sin**

Page No. :

- ESTIMATE REPAIR FOR -

Lee Wen Chie (Li WenQi)
966 Dunearn Road
#05-08

Singapore 589488

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SNA4712G	WBA6V120505T62176	24/06/2021	216i Gran Tourer	31376


DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
* To replace rear bumper and attachments, boot lid and attachments include knocking out dents caused by the accident	1,700.00	0.00	1,700.00	
To spray paint rear bumper and boot lid	1,826.00	0.00	1,826.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00	
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00	
To remove and install rear windscreen glass to facilitate repairs	574.00	0.00	574.00	
To conduct water leak tests	75.00	0.00	75.00	
* To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	504.00	0.00	504.00	
To remove and install boot compartment carpet and garnish to facilitate repair	257.00	0.00	257.00	
To carry out body cavity preservation (Per panel)	112.00	0.00	112.00	
Sundries	80.00	0.00	80.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,257.95	1.00	0.00	1,257.95
# EXPANDING NUT	1.05	4.00	0.00	4.20
REAR BUMPER CARRIER	490.70	1.00	0.00	490.70

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W





Final Report

REAR BUMPER PANEL PRIMED (LINES PDC)	1,088.30	1.00	0.00	1,088.30
LETTERING 216 I	65.60	1.00	0.00	65.60
GROMMET	0.80	2.00	0.00	1.60
PLAQUE 74MM	72.85	1.00	0.00	72.85
# BUMP STOP	3.45	10.00	0.00	34.50
REAR BUMPER TRIM STRIP CHROM	97.90	1.00	0.00	97.90
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	27.85	1.00	0.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	5,464.00
Total Parts :	3,430.70
Total Labour & Parts (before GST) :	8,894.70
Deduction for Excess :	
Total Repair Costs less Excess:	8,894.70
GST @8%:	711.58
Grand Total :	9,606.28

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

