

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22012823/UNY3Q2**Date:** 06/01/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000276
Claimant Vehicle No :	SHA2506U	Insured Vehicle No :	SLF7386S
Date of Loss:	22/12/2022	Nature of Claim:	TP
		Claim No:	M2207344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2506U	Engine No:	D4FDGU672455
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU093610
Reg. Date:	29/09/2016 (Man. Year: 2016)	Odometer:	693123 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,913.20	2,007.36	1,905.84	48.70
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,250.00	1,390.00	860.00	38.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,174.20	3,408.36	2,765.84	44.80
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	6,174.20	2,700.00	3,474.20	56.27
+ GST 7.00/7.00% (S\$)	432.19	189.00	243.19	56.27
Nett Amount (S\$)	6,606.39	2,889.00	3,717.39	56.27

INSPECTION

Date of Assignment:	23/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	23/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2506U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER	Cut / Deformed	1,052.20 FL	*1,052.20 FL	
2	1		*FRT BUMPER SIDE BRKT LH	Bent	24.60 FL	*24.60 FL	
3	1		*FRT BUMPER UPPER BRKT LH	Bent	22.40 FL	*22.40 FL	
4	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL	
5	1		*FRT FENDER LH	Repair	663.00 FL	*- FL	
6	1		*HEADLAMP LH	Cracked	1,388.00 FL	*1,388.00 FL	
7	1		*HEADLAMP SUPPORT PANEL	Repair	907.40 FL	*- FL	
8	1		*FRT WHEEL APRON LH	Repair	637.00 FL	*- FL	
9	1		*FRT FENDER SHIELD LH	Not Necessary	174.90 FL	*- FL	
					Sub Total (\$\$)	4,891.50	2,509.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	978.30	501.84
					Total Parts (\$\$)	3,913.20	2,007.36

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	560.00
2	SPRAY PAINTING - BONNET & Etc	New	900.00	750.00
3	TUFF KOTE	New	60.00	0.00
4	CHECK LIGHTINGS	New	60.00	20.00
5	WHEEL ALIGNMENT	New	120.00	0.00
6	TOWING FEE	New	60.00	60.00
7	R/I AIR CON CONDENSER ETC	New	150.00	0.00
			Gross Labour Cost (\$\$)	2,250.00
				1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >