

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22012829/UWY3Q2**Date:** 01/02/2023**REFERENCE**

Insured/Claimant: LEO MAY LIN Policy No: DMPCSNA00265062201

Date of Loss: 21/12/2022 Nature of Claim: OD Claim No: SNM22D209177/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML5983M**
 Make & Model: KIA STONIC, 998cc DCT SR (A) Engine No: G3LCKP039609
 Reg. Date: 28/05/2019 (Man. Year: 2019) Chassis No: KNAD6811VK6303496
 Colour: Grey Odometer: 59133 km
 Engine Capacity: 998 cc
 Market Value/New Car Price: S\$76,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm
 Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,390.00	3,440.00	950.00	21.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	658.50	765.70	-107.20	-16.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,048.50	4,205.70	842.80	16.69
- Excess (\$\$)	0.00	200.00	-200.00	
(\$\$)	5,048.50	4,005.70	1,042.80	20.66
+ GST 7.00/7.00% (\$\$)	353.40	280.40	73.00	20.66
Nett Amount (\$\$)	5,401.90	4,286.10	1,115.80	20.66

INSPECTION

Date of Assignment: 23/12/2022 Present Location: Jin Auto Services Pte Ltd (Defu)
 Date Inspected: 28/12/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)
 Estimated Period of Repair: 4.0 days Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	143	KIA STONIC 998cc DCT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML5983M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts 4,390.00		4,390.00 F	*3,440.00 F
F=Franchise part.						
Total Parts (S\$)					4,390.00	3,440.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total of Labour 231.00	New	231.00	338.20
2	Total Paint Including Material 427.50	New	427.50	427.50
Gross Labour Cost (S\$)			658.50	765.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >