



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|---|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR22012830/Uvy3m4 Date: 27/04/2023 Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHB 1209D | Veh. Inspected | SNH 5300T |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | TAX/12/22/2046 | Excess (\$) | 0.00 |
| | Assign From | ANA | Assign Date | 23/12/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA SIENTA (A) | c.c | 1496 |
| | Engine No. | HIDDEN | Year of Reg. | 2018 |
| | Chassis No. | MHFZ28H3100051025 | Colour | GREY |
| | Odometer | 70574 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/45 ZR17 | TOYO | 5 mm |
| | L/H Front Tyre | 215/45 ZR17 | TOYO | 5 mm |
| | R/H Rear Tyre | 215/45 ZR17 | TOYO | 5 mm |
| | L/H Rear Tyre | 215/45 ZR17 | TOYO | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 17/12/2022 | Inspection Date | 20/03/2023 |
| | Survey held at | BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |