

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIS22012838/4x3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBK 17714

at Workshop m/s

3411

of

Insured:

SMN 251X

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒ N/S	☐ O/S
☐	☐

Bal. or Market Value:

\$ 6800

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 81338

Veh No:

FBK 17714

Yr Regn:

13/04/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha F28-S c.c. 779

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

29/01

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JYARN25F 000000758

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70 ZR 17

R:

150/55 ZR 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/12/22

D.O.I.

27/12/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

col. until 12-04-2025 & 2 yrs. 3mths
 1/5 & 5200 base on calculation reduce some more to 51c.
 2/5 & 5000 in hand Raymond

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))



BAN HOCK HIN
Co., Pte Ltd

Mech: KC

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 42410

- Rev. 1

ALLIANZ INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN: Motor Claim Department

DATE : 23/12/2022
CLAIM NO. : 12074
POLICY NO. : P20557454R01

FROM : STEPHANIE


VEHICLE NO. : FBK1771U
MAKE/MODEL : YAM / FZ8S

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 40127 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	91.00
2	BEARING SWINGARM 2 P/N: 61932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
3	BEARING SWINGARM 3 P/N: 61944 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00
4	BELLY PAN (AFTERMARKET) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$376.00	376.00
5	BOLT CAP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$310.00	310.00
6	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$230.00	230.00
7	BOX SIDE (GIVI) E22N (BLACK) P/N: 49418 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$400.00	800.00
8	BUSH SWING ARM P/N: 61946 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$77.00	77.00
9	COVER 5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$184.00	184.00




bizSAFE₃




Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COVER BRACKET FOOTREST FRONT P/N: 61941 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00 ✓
11	COVER MAGNETO ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$121.00	121.00 ✓
12	COVER PEDAL SHIFT P/N: 50524 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00 ✓
13	COVER TAIL REAR P/N: 61933 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$271.00	271.00 ✓
14	COVER TANK CENTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$310.00	310.00 ✓
15	COWLING FRONT ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$800.00	800.00 ✓
16	DAMPER COVER FUEL TANK 2 P/N: 70474 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$6.00	24.00 ✓
17	DAMPER FUEL TANK P/N: 61947 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00 ✓
18	DAMPER RUBBER 1 P/N: 70461 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00 ✓
19	FOOTREST FRONT ASSY RH P/N: 70453 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	73.00 ✓
20	GASKET CRANKCASE COVER P/N: 43049 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00 ✓
21	HANDGUARD (AFTERMARKET) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$150.00	150.00 ✓
22	HOLDER DAMPER LH P/N: 63342 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$31.00	62.00 ✓
23	LABOUR P/N: 06766 - (REPORTED BY MECHANIC)	Supply/Install	18.00	\$69.00	1,242.00 ✓
24	LAMP SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00 ✓
25	LAMP SIGNAL REAR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00 ✓

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
26	LOGO (YAMAHA) (LARGE) P/N: 39544 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	1.00 35.00
27	MIRROR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$136.00	1.00 136.00
28	MIRROR RH P/N: 40140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$147.00	1.00 147.00
29	MUFFLER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,555.00	1.00 1,555.00
30	O-RING P/N: 28870 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	1.00 5.00
31	O-RING (FUEL PUMP) P/N: 46833 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	1.00 38.00
32	PANEL INNER RH P/N: 40143 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	1.00 140.00
33	PEDAL BRAKE P/N: 70462 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	1.00 63.00
34	PLUG P/N: 51933 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	1.00 17.00
35	SEAL 3 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	1.00 11.00
36	SEAL 4 P/N: 72806 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	1.00 11.00
37	SEAL 5 P/N: 72804 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	1.00 11.00
38	SEAL 6 P/N: 72801 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	1.00 11.00
39	SEAL COVER FUEL TANK P/N: 70473 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	1.00 5.00
40	SEAL GUARD P/N: 74005 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$115.00	1.00 115.00
41	SLIDER FRAME (MOTOVATION) P/N: 61937 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$150.00	1.00 150.00

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
42	STICKER COVER SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
43	STICKER WARNING YAMAHA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
44	SWING ARM P/N: 61943 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,138.00	2,138.00
45	TANK FUEL P/N: 61936 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,610.00	1,610.00
46	WASHER THRUST SWINGARM P/N: 53809 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$19.00	38.00
SUB TOTAL					\$11,591.00
GST @ 7 %					\$811.37
GRAND TOTAL (SGD)					\$12,402.37

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 43379

Supplementary 1 To QTN: 42410

DATE : 27/04/2023
CLAIM NO. : 12074
POLICY NO. : P20557454R01
FROM : RAYMOND

Customer :

ALLIANZ INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD #09-01
SINGAPORE 068897

VEHICLE NO. : FBK1771U
MAKE/MODEL : YAM / FZ8S

S/N	Description	Action	Qty	Unit Price	Amount
1	REPAIR & SPRAY ^{29.47M} FUEL TANK	Spray	1.00	\$280.00	280.00
SUB TOTAL					\$280.00
GST @ 8 %					\$22.40
GRAND TOTAL (SGD)					\$302.40

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*43379 *

bizSAFE₃

