

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

Email: willybjt@gmail.com / Mobile: 96699986**INVOICE**

Mr. Ong Seng Kiat
Block 776 Yishun Avenue 2 #12-1591
Singapore 760776

Invoice No : PA/2205/0003/tpw
Our Ref : PA/FBS9405/0422/tpw
Date : 09 May 2022

Claim Type	Third Party	Date of Accident	07 April 2022
Vehicle No.	FBS 9405 H	Date of Inspection	28 April 2022
No	Description	Amount (S\$)	
1	Survey fees inclusive of Transportation and Photographs (60) copies	\$500.00	
	Total	\$500.00	
Singapore Dollar: Five Hundred Only			
Terms of Payment - Within 30 (Thirty) days after receiving our Final Report & Invoice Payment payable as follows and kindly indicate Invoice No.			
<ul style="list-style-type: none">• Cheque - Payable to Prudent Adjustors Services• Bank Transfer - DBS 025-902513-4• Paynow - UEN No 53193457LBJT			


Prudent Adjustors Services
Bok Jee Tan

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Email: willybjt@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Ong Seng Kiat
Block 776 Yishun Avenue 2 #12-1591
Singapore 760776

Our Ref : PA/FBS9405/0422/tpw
Date : 09 May 2022

REFERENCES

Claim Type	: Third Party	Date of Accident	: 07 April 2022
Vehicle No	: FBS 9405 H	Date of Assignment	: 28 April 2022
Make	: Yamaha	Date of Inspection	: 28 April 2022
Model	: Aerox155 CVT	Date of Re-inspection	: 29 & 30 April 2022
Registration Date	: 16 September 2021	COE Expiry	: 15 September 2031
Color	: Grey	Chassis No	: MH3SG6410LJ006293
Odometer	: 11,355km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	IRC	110/80-14	6mm
Rear	IRC	140/70-14	8mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and right sides.
Please refer to photographs and assessment of repairs for details
Enclosed (60) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$3,746.13 Revised Assessment : \$3,000.00 Lump sum

Survey conducted at Bike Dynamic Centre

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Four (4) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note: The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock reconditioned parts whichever is possible


PRUDENT ADJUSTORS SERVICESVehicle No: **FBS 9405 H**

Our Ref: PA/FBS9405/0422/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>S/N</u>	<u>Description Material</u>	<u>Qty</u>	<u>Condition</u>	<u>Original Quotation</u>	<u>Revised Quotation</u>
1	Front visor	1 pc	Serviceable	67.50	~
2	Front centre panel	1 pc	Hdr cracked	145.00	145.00
3	Front cowling stay	1 pc	Bent	89.60	89.60
4	Body cowling LH/RH @ 167.50/-	2 pcs	Cut	335.00	335.00
5	Body cowling inner panel (Mat black)	1 pc	Hdr cracked	121.50	121.50
6	Front fork assy @ \$446.50/-	2 pcs	Bent	893.00	893.00
7	Fork under bracket complete	1 pc	Distorted	205.00	205.00
8	Front wheel rim	1 pc	Warped	380.00	380.00
9	Foot step board RH	1 pc	Cut	120.50	120.50
10	Footrest board lower side cover RH	1 pc	Cut	128.60	128.60
11	Muffler protector	1 pc	Cut	110.00	110.00
				2,595.70	2,528.20
List price less discount 10%				259.57	252.82
				2,336.13	2,275.38
<u>Add special nett item</u>					
12	Steering cone & bearing	1 set	Necessary	210.00	105.00
13	Body sticker	1 set	Necessary	150.00	120.00
				360.00	225.00
<u>Labour</u>					
Chassis frame align				550.00	450.00
Workmanship				500.00	400.00
				1,050.00	850.00
Total parts & labour concluded				<u>3,746.13</u>	<u>3,350.38</u>
Lump sum repair adjustment (less 10% due to no used parts)					<u><u>3,000.00</u></u>

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan