

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
Mr Cheng Tat Ming
Blk 33 Kovan Road #02-38

Singapore 545020

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Cheng Tat Ming

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 22/12/2022
WIP No. . : 55785
Veh.In/Out:
*Tel.No. . : Mobile: 97457055
Reg.No. . : SLL50508
Reg.date . : 27/07/2021
Mileage . : 0
Chassis No: SADHA2A12K1F71979

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, 013w FRT FENDER LH, HEADLAMP LH, ETC		0	3000.00	0		3,000.00	S
800	TO SPRAY FRT BUMPER, FRT FENDER LH		0 2000	2500.00	0		2,500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	621.00	0		621.00	S
280	TO FOCUS HEADLAMP		0	207.00	X0		207.00	S
0031	TO REPLACE LHF RIM		0	50.00	0		50.00	S
419	WHEEL ALIGNMENT		0	280.00	0		280.00	S
	COVER-BUMPER repair	1.0	EA	2633.30			2,633.30	S
	BRACKET-FENDR/BUMPR X nn	1.0	EA	83.20			83.20	S
	PANEL-FENDER LH repair	1.0	EA	1496.80			1,496.80	S
	LINER-WHEELARCH LH X nn	1.0	EA	416.80			416.80	S
	HEADLAMP LH X nn	1.0	EA	12795.80			12,795.80	S
	WHEEL-ROAD-ALLOY Sca /	1.0	EA	4642.90	4178.61		4,642.90	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Cheng Tat Ming

Blk 33 Kovan Road #02-38

Singapore 545020

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Cheng Tat Ming

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 22/12/2022

WIP No. . : 55785

Veh.In/Out:

*Tel.No. . : Mobile: 97457055

Reg.No. . : SLL5050S

Reg.date . : 27/07/2021

Mileage ... : 0

Chassis No: SADHA2A12K1F71979

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BADGE X	1.0 EA	176.30			176.30	S

Pass

Hp 9000068

4 days

28/12/22 @ 1100

Resy after repair

To take new rim

Labour Total	6,658.00
Parts Total	22,245.10
Package Total	0.00

Gross Total. 28,903.10

Net..... 28,903.10

GST @ 7.0% 2,023.22

Total..... 30,926.30

Paid..... 0.00

Please Pay.. 30,926.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated