

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 12 Jun 2023

Preliminary Advice

Insured Vehicle No	: XD7722Z	Accident Date	: 23/12/2022
TP Vehicle No	: SJL6151B	Assignment Date	: 27/12/2022
Make	: KIA RIO	Est. Duration of Repair	: 6
Date of Inspection	: 27/12/2022		
Inspection At	: UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,839.25
Revised Amount	:S\$	3,370.87
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,370.87
 Lump Sum Repair	 :S\$	 2,700.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	15,094.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,906.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.