



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT
No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
TELEPHONE: 6748 2795 FAX: 6747 2373
Registration No.: 203165/00D

TP MS16.

Hui Rong

LKK

DATE: 28/12/2022 OUR REF: UAPL1572
REPAIR ESTIMATE TO THE KIA RIO NO SJL6151B

1 R/H FRONT DOOR ASSY <i>new</i>	\$ 1,044.20 <i>X</i>
1 R/H FRONT DOOR PROTECTOR <i>new</i>	\$ 315.20 <i>X</i>
3 R/H FRONT DOOR BLACK STICKER <i>new</i>	\$ 135.00 <i>X (sn)</i>
1 R/H REAR DOOR ASSY <i>new</i>	\$ 899.40 <i>X</i>
2 R/H REAR DOOR HINGES <i>new</i>	\$ 188.40 <i>X</i>
1 R/H REAR DOOR LOCK <i>new</i>	\$ 287.60 <i>X</i>
1 R/H REAR DOOR WEATHERSTRIP <i>new</i>	\$ 156.20 <i>X</i>
1 R/H REAR DOOR PROTECTOR <i>new</i>	\$ 315.20 <i>X</i>
3 R/H REAR DOOR BLACK STICKER <i>new</i>	\$ 135.00 <i>X (sn)</i>
1 R/H REAR DOOR CHECKER <i>new</i>	\$ 74.20 <i>X</i>
1 R/H REAR FENDER PANEL <i>new</i>	\$ 936.80 <i>X</i>
1 R/H REAR SHOCK ABSORBER <i>new</i>	\$ 310.40 <i>X</i>
1 R/H REAR BEARING HUB <i>new</i>	\$ 344.50 <i>X</i>
1 R/H REAR HUB ASSY <i>new</i>	\$ 290.40 <i>X</i>
	<i>1534.30</i>
	<i>1380.87</i>
	<i>S.N: 60</i>
	\$ 5,432.50
	\$ 543.25
	<u>\$ 4,889.25</u>

LESS 10%.....

SPECIAL NETT:-

- 1 R/H SPORT RIM *Wt*
1 R/H CENTRE LOWER SIDE SKIP *Ryis*

\$ 480.00 *X*
\$ 600.00 *X*

480

LABOUR CHARGES:-

- TO DISM/RENEW UNDERCARRIES IN REPAIR
TO DISM/REWIRE DAMAGED PORTION
TO COMPLETE WHEEL ALIGNMENT
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
TO PUTTY AND RESPRAY DAMAGED PORTION
TO SPRAY UNDERCOATING IN REPAIR

\$ ~~280.00~~ *80*
\$ ~~120.00~~ *30*
\$ ~~150.00~~ *80*
\$ ~~1,200.00~~ *500*
\$ ~~1,000.00~~ *700*
\$ ~~120.00~~ *40*
\$ 8,839.25

1430

total: *3370.87*

L/S: *2.7K*

06 Days

2.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: