

(09/11/11) waf

ASS. REC. BY: P. J. J.REF: C3/AH122012860/Rvy3C
104M**ASSIGNMENT**

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 9990Cat Workshop m/s EM-1of 160, SIN MINH DR #05-21Insured: AGI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 43k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: 1N / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 27KVeh No: GBF 9990CYr Regn: 2016 / July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HIACE 50R M c.c. 2982Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 170 518 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P500200934Gen. Cond: Good / Kak / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NIH / STD A/Rim orTyre Size: F: 195R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 01/12/22 D.O.I. 28/12/22Survey held at EM-1Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS \$I

Photos

Others

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBF 9990C
Vehicle Model : TOYOTA HIACE
Accident Date : 01.12.2022
Original Reg Date : 22.07.2016

Date : 23.12.2022
Chassis : JTFHT02P500200934
TP Ins. **BUDGET DIRECT**

ESTIMATE

1	1 pc	Tailgate <i>lt</i>		1,650.90
2	1 pc	Tailgate Badge <i>m</i>		62.00
3	1 pc	Tailgate Sticker TOYOTA HIACE <i>m</i>		56.00
4	1 pc	Tailgate Outer Garnish <i>X</i>		197.20
5	1 set	Tailgate Outer Garnish Clips <i>X</i>		30.00
6	2 pcs	Tailgate Hinges <i>X</i>	85.90	171.80
7	2 pcs	Tailgate Absorber <i>X</i>	389.60	779.20
8	1 pc	Tailgate Inner Lock <i>lt</i>		461.60
9	1 pc	Tailgate Auto Lock Actuator <i>X</i>		456.20
10	1 pc	Tailgate Lock Catch <i>X</i>		42.00
11	1 pc	Tailgate Weatherstrip <i>m</i>		381.90
12	1 pc	Tailgate Inner Trim Board <i>cm</i>		235.60
13	1 set	Tailgate Inner Trim Board Clips <i>m</i>		40.00
14	1 pc	Taillamp <i>X</i>		297.20
15	1 pc	Taillamps Inner Sealer <i>X</i>		38.00
16	1 pc	Taillamp Bottom Corner Garnish LH ?		86.00
17	1 pc	Taillamp Bottom Corner Garnish Retainers <i>7?</i>		38.00
18	1 pc	Rear Bumper <i>de</i>		495.60
19	2 pcs	Rear Bumper Side Retainers <i>LH-? / RH-X 1pc</i>	69.20	138.40
20	1 set	Rear Bumper Clips <i>m</i>		50.00
21	4 pcs	Rear Bumper Stay <i>lt</i>	18.00	72.00
22	1 pc	End Panel (Inner) <i>rgm</i>		994.80
23	1 pc	End Panel (Outer) <i>lt</i>		492.50
24	1 pc	End Panel Top Plate <i>lt</i>		192.00
25	1 pc	Spare Tyre Carrier <i>X</i>		223.60
				7,682.50
Less 25%				1,920.63
				5,761.88

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBF 9990C

B/F

5,761.88

Special Nett

1	1 pc	Tailgate Sticker 70km/h	15.00	10
2	1 pc	Rear Windscreen Sealant	60.00	60
3	1 set	Rear Windscreen Inner Seal	50.00	60
4	1 set	Body Panel Joint Sealant	120.00	200
5	1 set	Reverse Sensor	250.00	35
6	1 pc	Rear Number Plate w/Holder	50.00	

Labour charge

1	Panel Beating	1,000.00	700
2	Spray painting	1,000.00	800
3	Check Wiring	50.00	30
4	Anti rust	90.00	50
5	Remove and install rear winscreen.	140.00	120
6	Remove and install tailgate parts.	90.00	60
7	Remove and install carpet and interior	120.00	X
8	Remove and install reverse sensor.	90.00	60
9	Remove and install reverse camera.	90.00	20

8,976.88

Less 20% 1,795.38

Lump sum 7,181.50

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene
Hy 90010068

67 days

4/5
28/12/22 @1350

Reg after
repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 104M

Vehicle Details

Vehicle No.: GBF9990C

Vehicle to be Exported: No

Intended Deregistration Date: 01 Dec 2022

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR
MANUAL

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: 1KD2631531

Chassis No.: JTFHT02P500200934

Maximum Power Output: -

Open Market Value: \$27,952.00

Original Registration Date: 22 Jul 2016

First Registration Date: 22 Jul 2016

Transfer Count: 0

Actual ARF Paid: \$1,398.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Jul 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$43,117.00

COE Rebate Amount: \$15,682.00

Total Rebate Amount: \$15,682.00

The information contained herein is correct as at 01 Dec 2022

OK

Toyota Hiace 3.0M

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price	\$43,800	Lifespan ?	28-Jul-2036
Depreciation ?	\$12,220 /yr View models with similar depre	Reg Date	29-Jul-2016 (3yrs 7mths COE left)
Mileage	N.A.	Manufactured ?	2016
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$14,100 as of today (change)	Fuel Type	Diesel
COE ?	\$39,346	OMV ?	\$27,741
Engine Cap	2,982 cc	ARF ?	\$1,388
Curb Weight	1,740 kg	No. of Owners	1