

SIN HWEE MOTOR PTD LTD

BLK 3023A UBI RD 1 #01-59
SINGAPORE 408717
UEN: 201327079M

Estimate

Date	Estimate #
28/12/2022	1023

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Name / Address

CHOI WAI MUN

Acknowledged by Repairer

Signature:

Date:

JM6BN22A8H0113362

VEHICLE NO	MODEL
SLL 5653 C	MAZDA 3

Description	Qty	Rate	Total
REAR BUMPER <i>Distorted</i>		1,170.00	1,170.00
REAR BUMPER REINFORCEMENT <i>Distorted</i>		563.00	563.00
SIDE RETAINER <i>Distorted</i>	2	45.00	90.00
REAR END PANEL <i>Distorted</i>		630.00	630.00
END PANEL TOP GARNISH <i>Distorted</i>		119.55	119.55
REAR BOOTLID <i>Distorted</i>		1,004.00	1,004.00
REAR BOOTLID LOCK <i>Distorted</i>		186.00	186.00
WEATHER STRIP <i>Distorted</i>		135.00	135.00
REVERSE SENSOR <i>Distorted</i>	2	258.00	516.00
TAILLAMP LIGHT R/H (BOOTLID) <i>Distorted</i>		289.00	289.00
REFLECTOR R/H <i>Distorted</i>		68.44	68.44
10 PCS BUMPER CLIP <i>Distorted</i>	10	4.50	45.00
TO SUPPLY FITTINGS AND INSTALL REVERSE SENSOR		80.00	80.00
TO DISMOUNT AND MOUNT INNER TRIMS, BOARDS TO FACILITATE REPAIR WORK		120.00	120.00
TO TRANSFER BOOTLID MECHANISMS, FITTINGS AND TRIMS TO NEW BOOTLID		180.00	180.00
TO REPLACE END PANEL INCLUDE KNOCKING, CUTTING AND WELDING TO REPLACE, INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.		450.00	450.00
TO SPRAY PAINT REAR BOOTLID, END PANEL, BUMPER AND REAR FENDER - PEARL WHITE		1,300.00	1,300.00
TO SUPPLY AND TUFF KOTE		200.00	200.00
TO CARRY OUT WIRE CHECKING		120.00	120.00

Total: 5413.19

h/s: 4.3K

Total

\$7,763.99

06 Days