

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #03-03 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Estimate No: MC1903227
 Date: 27 Dec 2022
 Policy No: D22MTPV01002783
 Veh Reg No: SKM1258T
 Make/Model: LEXUS ES250
 EXECUTIVE A/T

Your Ref No: SKM1258T
 Claim Type: Own Damage
 Accident Date: 22/12/2022

291.2

11-2 Not with air
 Revery B & pain
 4 days

Estimate Repair Cost to Vehicle No : SKM1258T

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BONNET		1 PC	75.00	X
2 RADIATOR GRILLE BASE		1 PC	460.00	—
3 RADIATOR GRILLE CLIPS		2 PC	3.00	—
4 RADIATOR GRILLE BUSH		2 PC	16.00	?
5 RADIATOR GRILLE CHROME MLDG		1 PC	165.00	—
6 RADIATOR GRILLE EMBLEM	(0.0)	1 PC	200.00	X X
7 RADIATOR GRILLE TOP RUBBER		1 PC	50.00	?
8 FRONT BUMPER		1 PC	380.00	—
9 FRONT BUMPER SIDE RETAINER LH & RH	also it	2 PC	80.00	4
10 FRONT BUMPER LOWER GRILLE		1 PC	310.00	?
11 FRONT BUMPER LOWER GRILLE TOW COVER	nsp	1 PC	40.00	X X
12 FRONT BUMPER LOWER GRILLE HOLE COVER LH & RH	also it	2 PC	50.00	4
13 FRONT BUMPER NO PLATE GARNISH	cm	1 PC (0.0)	60.00	X
14 FRONT BUMPER SPONGE		1 PC	70.00	2
15 FRONT BUMPER REINFORCEMENT		1 PC	200.00	2
16 HEADLAMP ASSY LH & RH	cls myom	2 PC	3,500.00	4
17 FOGLAMP LH & RH		2 PC	200.00	X
18 FOGLAMP COVER LH & RH		2 PC	120.00	X
19 FOGLAMP BKT LH & RH - CHECK PRICE		2 PC	0.0000	X
20 PARKING SENSOR CTR LH & RH		2 PC	310.00	?
21 PARKING SENSOR CTR CLIPS		2 PC	30.00	?
22 PARKING SENSOR CORNER LH & RH		2 PC	310.00	X
23 PARKING SENSOR CORNER CLIPS		2 PC	16.00	X
24 HORN LH & RH		2 PC	106.00	X
25 AIR CON CONDENSER ASSY		1 PC	770.00	?
26 RADIATOR ASSY		1 PC	750.00	?
27 RADIATOR FAN BLADE LH		1 PC	120.00	X
28 RADIATOR FAN BLADE RH		1 PC	150.00	X
29 RADIATOR FAN MOTOR LH		1 PC	180.00	X
30 RADIATOR FAN MOTOR RH		1 PC	265.00	X
31 RADIATOR FAN COWLING		1 PC	145.00	X
32 RADIATOR SPARE TANK		1 PC	105.00	X
33 RADIATOR SUPPORT PANEL		1 PC	570.00	?
34 RADIATOR SUPPORT PANEL TOP COVER		1 PC	130.00	✓
35 RADIATOR SUPPORT PANEL TOP COVER CLIPS		9 PC	13.50	✓
36 BRACE PANEL		1 PC	100.00	?
37 AIR GUIDE LH & RH		2 PC	160.00	?
38 AIR DUCT		1 PC	145.00	X
39 BATTERY TOP BKT		1 PC	50.00	X

Zila
 Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#03-03 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Your Ref No: SKM1258T
Claim Type: Own Damage
Accident Date: 22/12/2022

SURVEYOR COPY

Estimate No: MCI903227
Date: 27 Dec 2022
Policy No: D22MTPV01002783
Veh Reg No: SKM1258T
Make/Model: LEXUS ES250
EXECUTIVE A/T

Estimate Repair Cost to Vehicle No : SKM1258T

Description	U/Price	Quantity	Cost	Amount
40 FRONT FENDER COWLING LH & RH			<u>S\$</u>	<u>S\$</u>
41 FRONT FENDER COWLING CLIPS		2 PC	290.00	X
		12 PC	18.00	X
			10,712.50	
	Add 10%		1,071.25	11,783.75

Special Nett

42 NUMBER PLATE	(G.D.) 1 PC	35.00	X
43 RADIATOR COOLANT	1 PC	30.00	?
44 BATTERY - CHECK PRICE	1 PC	0.0000	X
			65.00

LABOUR

45 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
46 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	?
47 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	✓
48 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT BONNET, FRONT FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	4001
49 TO SPRAY FRONT BONNET, FRONT BUMPER, RADIATOR SUPPORT PANEL, FRT FENDER LH & RH.	1 PC	1,000.00	6001
			2,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ah Lim Motor Company