

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 10 Mar 2023

Preliminary Advice

Vehicle No	: SLV2073T	Accident Date	: 18/12/2022
Make	: MAZDA 5	Policy No.	: SP2003638569
Assignment Date	: 24/12/2022	Excess	: S\$3,000.00
Date of Inspection	: 27/12/2022	Est. Duration of Repair	: 08 DAYS
Inspection At	: SME MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,825.60
Revised Amount	:S\$	10,937.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,937.30
Lump Sum Repair	:S\$	7,650.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	40,601.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,399.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on check items/ Final cost of repair.