

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 28 Dec 2022

Preliminary Advice

Vehicle No	: SLV2073T	Accident Date	: 18/12/2022
Make	: MAZDA 5	Policy No.	: SP2003638569
Assignment Date	: 24/12/2022	Excess	: S\$3,000.00
Date of Inspection	: 27/12/2022	Est. Duration of Repair	: 08 DAYS
Inspection At	: SME MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,825.60
Revised Amount	:S\$	7,164.30
Check Items (Estimated)	:S\$	7,336.80
Total	:S\$	14,501.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	40,601.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,399.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.