

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD-640(12)
Policy No:	SP2003638569	Date of Loss:	18/12/2022
Vehicle Reg. No.:	SLV2073T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	VALIANT KHONG FARN BING		
Driver:	VALIANT KHONG FARN BING		
Make/Model:	MAZDA 5, 2.0 (A)	Vehicle Reg. Date:	26/12/2017
Vehicle Colour:	RED	Chassis No:	JM6CW1071H0126678
Engine No:	PE10527205		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Remarks:	VEHICLE IN, KINLDY ARRANGE FOR SURVEY.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	15,120.60
Miscellaneous Items	275.00
Labour	4,430.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,825.60
+ GST 7.00% (S\$)	1,387.79
Nett Amount (S\$)	21,213.39

This claim is handled by: WEN YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

not authorized
 here
 nearby
 Excess \$3000
 vehicle after repair
 2/3 = \$7650
 8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before letter spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV2073T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Bul</i>	0.00	0.00	*580.00 F
2	1		*FRT BONNET SEAL (WITH CLIPS) <i>twj</i>	0.00	0.00	*55.00 F
3	1		*FRT BONNET INSULATOR <i>11</i>	0.00	0.00	*135.00 F
4	8		*INSULATOR CLIPS <i>her</i>	0.00	0.00	*20.00 F
5	2		*FRT BONNET HINGE <i>her</i>	0.00	0.00	*90.00 F
6	1		*FRT BONNET LOCK <i>twj</i>	0.00	0.00	*115.00 F
7	1		*FRT BUMPER <i>DIJ</i>	0.00	0.00	*480.00 F
8	2		*FRT BUMPER RETAINER <i>on/mc</i>	0.00	0.00	*50.00 F
9	10		*FRT BUMPER CLIPS <i>her</i>	0.00	0.00	*25.00 F
10	1		*FRT BUMPER INNER SPONGE <i>on/f</i>	0.00	0.00	*105.00 F
11	1		*FRT BUMPER REINFORCEMENT <i>BD</i>	0.00	0.00	*350.00 F
12	1		*FRT BUMPER INNER BASE TOP <i>11</i>	0.00	0.00	*220.00 F
13	1		*FRT BUMPER LOGO <i>11</i>	0.00	0.00	*45.00 F
14	1		*FRT BUMPER CTR GRILLE <i>11</i>	0.00	0.00	*380.00 F
15	1		*FOG LAMP LH <i>11</i>	0.00	0.00	*180.00 F
16	1		*FOG LAMP GARNISH LH <i>11</i>	0.00	0.00	*55.00 F
17	2		*HEADLAMP <i>n/s 200 o/s 200</i>	0.00	0.00	*1,360.00 F
18	2		*HEADLAMP LOWER BRACKET <i>n/s 200 o/s 200</i>	0.00	0.00	*90.00 F
19	1		*HEADLAMP SUPPORT PANEL <i>11</i>	0.00	0.00	*380.00 F
20	1		*BRACE PANEL <i>11</i>	0.00	0.00	*38.00 F
21	1		*AIRCON CONDENSER <i>11</i>	0.00	0.00	*480.00 F
22	1		*RADIATOR <i>11</i>	0.00	0.00	*500.00 F
23	1		*RADIATOR FAN ASSY <i>11</i>	0.00	0.00	*680.00 F
24	1		*AIR DUCT <i>11</i>	0.00	0.00	*115.00 F
25	1		*AIR CLEANER BOX ASSY <i>11</i>	0.00	0.00	*225.00 F
26	1		* ISTOP CONTROL UNIT RH (CONVERTER) <i>11</i>	0.00	0.00	*420.00 F
27	1		*FRT FENDER LH <i>11</i>	0.00	0.00	*235.00 F
28	1		*FRT FENDER INNER COWLING LH <i>11</i>	0.00	0.00	*195.00 F
29	10		*INNER COWLING CLIPS <i>11</i>	0.00	0.00	*20.00 F
30	1		*FRT BUMPER UNDER COVER <i>11</i>	0.00	0.00	*195.00 F
31	1		*FRT FENDER TOP CORNER GARNISH LH <i>11</i>	0.00	0.00	*40.00 F
32	1		*SIDE SKIRT LH <i>11</i>	0.00	0.00	*580.00 F
33	15		*SIDE SKIRT CLIPS <i>11</i>	0.00	0.00	*75.00 F
34	1		*WIPPER GARNISH LH <i>11</i>	0.00	0.00	*130.00 F
35	1		*WPPER CORNER GARNISH LH <i>11</i>	0.00	0.00	*28.00 F
36	1		*FRT SHOCK ABSORBER LH <i>11</i>	0.00	0.00	*350.00 F
37	1		*FRT KNUCKLE ARM LH <i>11</i>	0.00	0.00	*280.00 F
38	1		*FRT KNUCKLE BEARING LH <i>11</i>	0.00	0.00	*115.00 F
39	1		*FRT LOWER ARM LH <i>11</i>	0.00	0.00	*210.00 F
40	1		*FRT ANTI ROLL BAR LINK LH <i>11</i>	0.00	0.00	*95.00 F
41	1		*FRT RACK END LH <i>11</i>	0.00	0.00	*115.00 F
42	1		*FRT TIE ROD END LH <i>11</i>	0.00	0.00	*115.00 F
43	1		*STEERING RACK <i>11</i>	0.00	0.00	*850.00 F
44	1		*STEERING CROSSMEMBER <i>11</i>	0.00	0.00	*1,750.00 F
45	1		*FRT LH SPORT RIM (ORI) <i>11</i>	0.00	0.00	*580.00 F
46	1		*LH ENGINE MOUNTING <i>11</i>	0.00	0.00	*185.00 F
47	1		*RH ENGINE MOUNTING <i>11</i>	0.00	0.00	*210.00 F
48	1		*REAR ENGINE MOUNTING <i>11</i>	0.00	0.00	*120.00 F
49	4		*AUTO OIL <i>11</i>	0.00	0.00	*100.00 F

F=Franchise part.

Sub Total (S\$)	13,746.00
+ Margin on L,N Items 10.00% (S\$)	1,374.60
Total Parts (S\$)	15,120.60

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT LH TYRE <i>SN</i>	235.00 <i>X</i>
2	1	FRT NUMBER PLATE <i>BAD</i>	40.00 <i>35</i>
Sub Total (S\$)			275.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 <i>✓</i>
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	New	350.00 <i>150</i>
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	180.00 <i>2</i>
5	REMOVE & REFIX ENGINE	New	350.00 <i>17 X</i>
6	4 WHEEL ALIGNMENT	New	100.00 <i>70</i>
7	REPROGRAMME ISTOP CONTROL UNIT	New	500.00 <i>11 X</i>
8	REMOVE & REFIX FUSE BOX LH	New	120.00 <i>11 X</i>
9	LABOUR CHARGE	New	1,400.00 <i>800</i>
10	SPRAY PAINTING	New	1,300.00 <i>800</i>
Gross Labour Cost (S\$)			4,430.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P-7893
+ 102

8682.30
35
2220

10937.1
302

7656