

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLV 2073T
at Workshop m/s: SMU
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: ?
(Client's Record)
Make of Veh: _____

Veh No: SLV 2073T Yr Regn: 26/12/17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: Mercedes c.c. 1998
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 179416 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JM6CW1071H0126678
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or affected
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Tyre Size: F: _____ R: 205/55-R16
BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 18/12/22 D.O.I. 27/12/22
Survey held at _____

Bal. or Market Value: 872k
IDAC Accident Rport: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: 30 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 998h
Date: _____ Person Contacted: L7A 40601
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rt & N/S Rt &
The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 13/12

Date/Time, File Pass to? : Preli. Report
1) : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format : _____
Lump Sum / I.B.I. (\$) _____

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD-640(12)
Policy No:	SP2003638569	Date of Loss:	18/12/2022
Vehicle Reg. No.:	SLV2073T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	VALIANT KHONG FARN BING		
Driver:	VALIANT KHONG FARN BING		
		Vehicle Reg. Date:	26/12/2017
Make/Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CW1071H0126678
Vehicle Colour:	RED		
Engine No:	PE10527205		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Remarks:	VEHICLE IN, KINDLY ARRANGE FOR SURVEY.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	15,120.60
Miscellaneous Items	275.00
Labour	4,430.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,825.60
+ GST 7.00% (S\$)	1,387.79
Nett Amount (S\$)	21,213.39

This claim is handled by: **WEN YING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

not authorized
 her
 name
 excess?
 whatsapp After repair
 2/5/23
 8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV2073T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>3ul</i>	0.00	0.00	*580.00 F
2	1		*FRT BONNET SEAL (WITH CLIPS) <i>TM</i>	0.00	0.00	*55.00 F
3	1		*FRT BONNET INSULATOR <i>11</i>	0.00	0.00	*135.00 F
4	8		*INSULATOR CLIPS <i>11</i>	0.00	0.00	*20.00 F
5	2		*FRT BONNET HINGE <i>11</i>	0.00	0.00	*90.00 F
6	1		*FRT BONNET LOCK <i>TM</i>	0.00	0.00	*115.00 F
7	1		*FRT BUMPER <i>DIJ</i>	0.00	0.00	*480.00 F
8	2		*FRT BUMPER RETAINER <i>cm/mc</i>	0.00	0.00	*50.00 F
9	10		*FRT BUMPER CLIPS <i>11</i>	0.00	0.00	*25.00 F
10	1		*FRT BUMPER INNER SPONGE <i>11</i>	0.00	0.00	*105.00 F
11	1		*FRT BUMPER REINFORCEMENT <i>11</i>	0.00	0.00	*350.00 F
12	1		*FRT BUMPER INNER BASE TOP	0.00	0.00	*220.00 F
13	1		*FRT BUMPER LOGO <i>11</i>	0.00	0.00	*45.00 F
14	1		*FRT BUMPER CTR GRILLE <i>TM</i>	0.00	0.00	*380.00 F
15	1		*FOG LAMP LH	0.00	0.00	*180.00 F
16	1		*FOG LAMP GARNISH LH <i>TM</i>	0.00	0.00	*55.00 F
17	2		*HEADLAMP <i>11/320 015?</i>	0.00	0.00	*1,360.00 F
18	2		*HEADLAMP LOWER BRACKET <i>11/320 015?</i>	0.00	0.00	*90.00 F
19	1		*HEADLAMP SUPPORT PANEL <i>11</i>	0.00	0.00	*380.00 F
20	1		*BRACE PANEL <i>11</i>	0.00	0.00	*38.00 F
21	1		*AIRCON CONDENSER	0.00	0.00	*480.00 F
22	1		*RADIATOR	0.00	0.00	*500.00 F
23	1		*RADIATOR FAN ASSY	0.00	0.00	*680.00 F
24	1		*AIR DUCT	0.00	0.00	*115.00 F
25	1		*AIR CLEANER BOX ASSY <i>cm</i>	0.00	0.00	*225.00 F
26	1		* ISTOP CONTROL UNIT RH (CONVERTER)	0.00	0.00	*420.00 F
27	1		*FRT FENDER LH <i>3ul</i>	0.00	0.00	*235.00 F
28	1		*FRT FENDER INNER COWLING LH <i>TM</i>	0.00	0.00	*195.00 F
29	10		*INNER COWLING CLIPS <i>11</i>	0.00	0.00	*20.00 F
30	1		*FRT BUMPER UNDER COVER	0.00	0.00	*195.00 F
31	1		*FRT FENDER TOP CORNER GARNISH LH <i>11</i>	0.00	0.00	*40.00 F
32	1		*SIDE SKIRT LH <i>11</i>	0.00	0.00	*580.00 F
33	15		*SIDE SKIRT CLIPS <i>11</i>	0.00	0.00	*75.00 F
34	1		*WIPPER GARNISH LH <i>11</i>	0.00	0.00	*130.00 F
35	1		*WPPER CORNER GARNISH LH <i>TM</i>	0.00	0.00	*28.00 F
36	1		*FRT SHOCK ABSORBER LH	0.00	0.00	*350.00 F
37	1		*FRT KNUCKLE ARM LH	0.00	0.00	*280.00 F
38	1		*FRT KNUCKLE BEARING LH	0.00	0.00	*115.00 F
39	1		*FRT LOWER ARM LH	0.00	0.00	*210.00 F
40	1		*FRT ANTI ROLL BAR LINK LH	0.00	0.00	*95.00 F
41	1		*FRT RACK END LH	0.00	0.00	*115.00 F
42	1		*FRT TIE ROD END LH	0.00	0.00	*115.00 F
43	1		*STEERING RACK <i>11</i>	0.00	0.00	*850.00 F
44	1		*STEERING CROSSMEMBER <i>11</i>	0.00	0.00	*1,750.00 F
45	1		*FRT LH SPORT RIM (ORI) <i>11</i>	0.00	0.00	*580.00 F
46	1		*LH ENGINE MOUNTING	0.00	0.00	*185.00 F
47	1		*RH ENGINE MOUNTING	0.00	0.00	*210.00 F
48	1		*REAR ENGINE MOUNTING	0.00	0.00	*120.00 F
49	4		*AUTO OIL	0.00	0.00	*100.00 F

F=Franchise part.

Sub Total (\$\$)	13,746.00
+ Margin on L,N Items 10.00% (\$\$)	1,374.60
Total Parts (\$\$)	15,120.60

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT LH TYRE <i>SN</i>	235.00 <i>X</i>
2	1	FRT NUMBER PLATE <i>B-10</i>	40.00 <i>35</i>
Sub Total (S\$)			275.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 <i>✓</i>
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	New	350.00 <i>150?</i>
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	180.00 <i>?</i>
5	REMOVE & REFIX ENGINE	New	350.00 <i>?</i>
6	4 WHEEL ALIGNMENT	New	100.00 <i>70</i>
7	REPROGRAMME ISTOP CONTROL UNIT	New	500.00 <i>?</i>
8	REMOVE & REFIX FUSE BOX LH	New	120.00 <i>?</i>
9	LABOUR CHARGE	New	1,400.00 <i>800</i>
10	SPRAY PAINTING	New	1,300.00 <i>900</i>
Gross Labour Cost (S\$)			4,430.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	998H
Vehicle Details	
Vehicle No.:	SLV2073T
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	PE10527205
Chassis No.:	JM6CW1071H0126678
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,074.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$17,074.00 <i>8537</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$11,951.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$28,650.00
Total Rebate Amount:	\$40,601.00

The information contained herein is correct as at 27 Dec 2022

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Subaru Forester 2.0A XT Sunroof.



2nd Car Used By The Mrs.
 Selling Due To Relocation. Only
 Serviced In Subaru.
 Direct Owner StarAd

PRIME MOTOR & LEASING
 (CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)
 With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Post an Ad Advertiser Login Ways of Selling

Sort by results/page

12 vehicles

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	mazda 5	Mazda 5 2.0A Sunroof	\$74,800	\$13,310 /yr	18-Dec-2017	1,998 cc	130,000 km	MPV	Available
		Service By Mazda Agent! Very Well Maintained By Previous Owner, Accident Free And In Pristine Condition, 100% In House Loan And Ba... Motor Universe Credit Pte Ltd Posted: 24-Dec-2022							
		Mazda 5 2.0A	\$80,000	\$14,350 /yr	18-Dec-2017	1,998 cc	57,000 km	MPV	Available
		Pearl white, beautiful original condition like new. Shelter parked. Family 2nd car. Used only to fetch children. New road tax. Posted: 21-Dec-2022 DIRECT OWNER							
		Mazda 5 2.0A Sunroof	\$73,800	\$14,010 /yr	21-Aug-2017	1,998 cc	80,000 km	MPV	Available
		Full loan available at \$1581, hassle free transaction with easy financing. 100% accident free, STA/Vicom evaluation welcomed! Contact... Hua Yang Credit Pte Ltd Posted: 21-Dec-2022							
		Mazda 5 2.0A Sunroof	\$70,800	\$14,520 /yr	13-Mar-2017	1,998 cc	81,100 km	MPV	Available
		One of the best cost efficient and spacious 7 seater MPV with dual sliding door.Pristine condition! No Repairs Needed! Lowest interest ra... Posted: 20-Dec-2022							
		KHY Motors Pte Ltd - Specialist for Mazda Car repair, servicing & maintenance KHY Motors strives to provide great customer service and great prices for all our customers! More info about this shop							
		Mazda 5 2.0A Sunroof	\$69,800	\$13,180 /yr	17-Aug-2017	1,998 cc	98,000 km	MPV	Available
		Pristine condition! 1 owner only! Full service and all wear and tear parts done up at Platinum Motoring in house workshop! 100% loan a... This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More Platinum Motoring Posted: 18-Dec-2022 PREMIUM AD							
		Mazda 5 2.0A Sunroof	\$73,800	\$13,760 /yr	18-Sep-2017	1,998 cc	105,399 km	MPV	Available
		Latest Arrival! 1 Owner,! Carefully driven and maintained by previous owner, 100% accident free, No repairs required, Flexible loan, Call... Horizon Motoring Posted: 18-Dec-2022							
		Mazda 5 2.0A Sunroof	\$70,800	\$13,030 /yr	03-Oct-2017	1,998 cc	87,951 km	MPV	Available
		Sporty white with premium black interior Mazda 5 Sunroof. Spacious 2.0L MPV suitable for both work and family use, comfortable 7 seat... Posted: 16-Dec-2022							

Compare