


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Xiao Chen

DATE : 24.12.2022

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKG6865P**
MODEL : **MERCEDES C180**
DATE OF ACCIDENT : 24.12.2022
TIME OF ACCIDENT : 11:05 HRS

WDD2050402R185206

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,191.00	\$ 2,191.00 <i>1890.</i>
2	REAR BUMPER CENTRE FRAME <i>Distorted</i>	1	\$ 232.00	\$ 232.00
3	REAR BUMPER TOWING COVER <i>Not new</i>	1	\$ 88.00	\$ 88.00 <i>X.</i>
4	REAR BUMPER EXHAUST COVER GARNISH <i>Distorted</i>	1	\$ 138.00	\$ 138.00
5	REAR BUMPER REVERSE SENSOR <i>2 pieces dist</i>	4	\$ 265.00	\$ 1,060.00 <i>530.</i>
6	REAR BUMPER REVERSE SENSOR HOLDER <i>New</i>	6	\$ 67.00	\$ 402.00 <i>120.</i>
7	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>New</i>	1	\$ 798.00	\$ 798.00 <i>X.</i>
8	REAR BUMPER CENTER UPPER BRACKET <i>could</i>	2	\$ 78.00	\$ 156.00
9	REAR BUMPER BOTTOM CENTER GARNISH <i>Distorted</i>	1	\$ 185.00	\$ 185.00
10	REAR BUMPER LOWER GARNISH <i>Distorted</i>	1	\$ 285.00	\$ 285.00
11	REAR BUMPER LOWER GARNISH CHROME <i>could</i>	1	\$ 346.00	\$ 346.00
12	REAR BUMPER UPPER CORNER BRACKET <i>could</i>	2	\$ 179.00	\$ 358.00
13	REAR BUMPER SIDE RETAINER <i>2nd</i>	2	\$ 74.00	\$ 148.00
14	REAR BUMPER LOWER BRACKET (CENTER) <i>could</i>	2	\$ 65.00	\$ 130.00
15	REAR BUMPER SMART SENSOR CONTROL UNIT <i>2nd</i>	1	\$ 374.00	\$ 374.00
16	REAR BUMPER SMART SENSOR <i>2nd</i>	1	\$ 169.00	\$ 169.00
17	REAR BUMPER SMART SENSOR C/W CABLE <i>New</i>	1	\$ 279.00	\$ 279.00 <i>X.</i>
18	REAR BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 658.00	\$ 658.00
19	REAR FENDER COWLING <i>Not new</i>	2	\$ 198.00	\$ 396.00 <i>X.</i>

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKG6865P**
 MODEL : **MERCEDES C180**
 DATE OF ACCIDENT : 24.12.2022
 TIME OF ACCIDENT : 11:05 HRS

20	REAR FENDER INNER TRIM <i>Not m</i>	2	\$ 425.00	\$ 850.00	+
21	REAR FENDER DRAIN GARNISH <i>Not m</i>	2	\$ 247.00	\$ 494.00	+
22	TAILLAMP <i>Crashd</i>	2	\$ 762.00	\$ 1,524.00	+
23	TAILLAMP PANEL LH <i>Repair</i>	1	\$ 986.00	\$ 986.00	+
24	BOOTLID <i>Dented</i>	1	\$ 2,450.00	\$ 2,450.00	+
25	BOOTLID HINGE <i>Not m</i>	2	\$ 311.00	\$ 622.00	+
26	BOOTLID CENTER MOULDING <i>Crashd. Not m</i>	1	\$ 159.00	\$ 159.00	+
27	BOOTLID LOGO <i>3 Mm</i>	1	\$ 48.00	\$ 48.00	+
28	BOOTLID EMBLEM 'C180'	1	\$ 86.00	\$ 86.00	+
29	BOOTLID TOP LOCK <i>Dand</i>	1	\$ 300.00	\$ 300.00	+
30	BOOTLID LOWER LOCK <i>Not m</i>	1	\$ 48.00	\$ 48.00	+
31	BOOTLID WEATHER STRIP <i>Cr</i>	1	\$ 189.00	\$ 189.00	+
32	BOOTLID NUMBER PLATE LAMP GARNISH <i>Not m</i>	1	\$ 168.00	\$ 168.00	+
33	REAR END PANEL <i>Distorted</i>	1	\$ 1,460.00	\$ 1,460.00	+
34	REAR END PANEL INNER GARNISH <i>Crashd</i>	1	\$ 285.00	\$ 285.00	+
35	REAR FLOOR PANEL TOP BORD <i>Crashd</i>	1	\$ 563.00	\$ 563.00	+
36	REAR FLOOR PANEL MAT <i>Not m</i>	1	\$ 288.00	\$ 288.00	+
37	REAR FLOOR WELL PANEL <i>Crashd.</i>	1	\$ 643.00	\$ 643.00	+
38	REAR FLOOR WELL PANEL BOTTOM SIDE GARNISH RH <i>torn</i>	1	\$ 165.00	\$ 165.00	+
39	REAR EXHAUST BOX <i>Best.</i>	1	\$ 1,630.00	\$ 1,630.00	+
40	REAR EXHAUST INSULATOR <i>Not m</i>	2	\$ 196.00	\$ 392.00	+
41	REAR EXHAUST SIDE INSULATOR <i>Not m</i>	2	\$ 155.00	\$ 310.00	+
42	REAR EXHAUST MOUNTING <i>Not m</i>	4	\$ 97.00	\$ 388.00	+
43	REAR EXHAUST MOUNTING BRACKET <i>Not m</i>	2	\$ 75.00	\$ 150.00	+

14681
1321250

TOTAL PRICE \$ 22,591.00
 LESS 10% \$ 2,259.10
SUB TOTAL PRICE \$ 20,331.90

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best.</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (SET) <i>Nec.</i>	1	\$ 50.00	\$ 50.00
3	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00
4	REAR BUMPER LOWER GARNISH CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00
5	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00

TO : ECICS MOTOR CLAIMS DEPTS
 VEHICLE NO : SKG6865P
 MODEL : MERCEDES C180
 DATE OF ACCIDENT : 24.12.2022
 TIME OF ACCIDENT : 11:05 HRS

6	BOOTLID SEALANT <i>Not Nec</i>	1	\$ 150.00	\$ 150.00	X
7	BOOTLID INSULATOR CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	X
8	BOOTLID CENTER MOULDING CLIP <i>Nec</i>	1	\$ 50.00	\$ 50.00	X.
9	BOOTLID NUMBER PLATE LAMP GARNISH CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	X.
10	BOOT LID EMBLEM 'C&C' <i>Nec</i>	1	\$ 120.00	\$ 120.00	40.
11	TAILLAMP CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	40.
12	REAR FENDER DRAIN GARNISH CLIP (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00	X
13	REAR FENDER COWLING CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	X
14	REAR FENDER INNER TRIM CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	X.
15	REAR END PANEL INSULATION SEAL <i>Nec</i>	1	\$ 150.00	\$ 150.00	60.
16	REAR END PANEL INNER GARNISH CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	10.
17	REAR FLOOR UNDER SIDE GARNISH CLIP RH (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00	20.
18	REAR FLOOR WELL PANEL SEALANT <i>Nec</i>	1	\$ 180.00	\$ 180.00	60.

TOTAL \$ 1,440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	1000.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800.
3	TUFF COAT	\$ 350.00	60.
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 380.00	60.
6	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
8	REMOVE AND REFIX AND RESET BOOTLID AUTO SYSTEM	\$ 250.00	60.

380

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKG6865P**
MODEL : **MERCEDES C180**
DATE OF ACCIDENT : 24.12.2022
TIME OF ACCIDENT : 11:05 HRS

9	REMOVE AND REFIX REAR FLOOR WELL PANEL	\$ 350.00	60
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 350.00	80
11	REAR CHASSIS ALIGNMENT	\$ 250.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	100

TOTAL

\$6,340.00

TOTAL PARTS COST : \$ 21,771.90
TOTAL LABOUR COST : \$ 6,340.00
TOTAL REPAIR COST : \$ 28,111.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2310 Adrian Ling.
H/S 27/12/22.
08 days.
total: 15902.80
H/S: 12.71 ✓