

ASS. REC. BY:

REF:

AIS / 22012874/Kny3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

25/12 813445.20 Centre (Red, 15018.78, 5270)

Veh No:

SMU 8691M

Yr Regn:

09, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Opel Astra

C.C.

1598

Colour

M.D. Green

A/C:

Insured / Std / NI / NA

Sp. Reading

133259

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W0VB08EG8K 8058191

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F. Wanli

Duraturn 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

13/12/22

D.O.I.

27/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. St

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	13/12/2022
Vehicle Reg. No.:	SMU8691M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL ASTRA ST, 1.6 D TURBO DIESEL (A)	Vehicle Reg. Date:	01/09/2020
Vehicle Colour:	GREEN	Chassis No:	W0VBD8EG8K8058191
Engine No:	A3191549L8GX0277		
Odometer:	225500 KM		
Paint Type:			<i>Not Authorized</i>
Total Loss?	NO		<i>Requiring B4 paint</i>
Est. Duration of Repair (day)	<i>86</i>		<i>Excess \$1500</i>
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		<i>\$13,445.20</i>

COST OF CLAIMS

	Amount
Parts	14,089.68
Miscellaneous Items	175.00
Labour	3,790.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	18,054.68
- Excess (S\$)	2,000.00
(S\$)	16,054.68
+ GST 7.00% (S\$)	1,123.83
Nett Amount (S\$)	17,178.51

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2022)
Parts:	144	OPEL ASTRA ST 1.6 D TURBO DIESEL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Munich Autocare Pte Ltd/SMU8691M/24/12/2022 12:41	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	39054067	*FRONT BONNET 1060.80	R 0.00	0.00	*1,023.00 F	✓
2	1	39032149	*FRONT BONNET HINGLE LH 32	Di 0.00	0.00	*32.00 F	2
3	1	39032150	*FRONT BONNET HINGLE RH 32	Di 0.00	0.00	*32.00 F	2
4	1	39081894	*FRONT HEADLAMP LH 487.20	m/c 0.00	0.00	*665.60 F	2
5	1	39081895	*FRONT HEADLAMP RH 487.20	CM 0.00	0.00	*665.60 F	✓
6	1	39058200	*FRONT HEADLAMP LOWER BRACKET LH 48.80	CM 0.00	0.00	*65.00 F	2
7	1	39058201	*FRONT HEADLAMP LOWER BRACKET RH 48.80	CM 0.00	0.00	*65.00 F	2
8	1		*FRONT HEADLAMP ABSORBER BRACKET LH	R 0.00	0.00	*65.00 F	X
9	1		*FRONT HEADLAMP ABSORBER BRACKET RH	R 0.00	0.00	*65.00 F	X
10	1	39086891	*FRONT FENDER BRACKET LH	R 0.00	0.00	*22.40 F	X
11	1	39086892	*FRONT FENDER BRACKET RH	R 0.00	0.00	*22.40 F	X
12	1	39052728	*FRONT BUMPER 1035.20	R 0.00	0.00	*1,632.80 F	✓
13	1	39089229	*FRONT RADIATOR GRILLE 340	CM 0.00	0.00	*400.00 F	✓
14	1	39132771	*FRONT RADIATOR GRILLE INNER BASE 99.20	CM 0.00	0.00	*400.00 F	✓
15	1	39086922	*FRONT GRILLE LOGO 87.20	CM 0.00	0.00	*109.00 F	✓
16	1	13423641	*FRONT RADIATOR GRILLE MOULDING CHROME LH	Sn 0.00	0.00	*166.00 F	X
17	1	13423642	*FRONT RADIATOR GRILLE MOULDING CHROME RH	Sn 0.00	0.00	*166.00 F	X
18	1	39089220	*FRT LOW CENTRE GRILLE 117.60	Di 0.00	0.00	*138.00 F	✓
19	4	13447589	*FRONT PARKING SENSOR	Sn 0.00	0.00	*320.00 F	X
20	1	39086895	*FRONT BUMPER RENTAINER LH	Sn Di 0.00	0.00	*31.20 F	4
21	1	39086896	*FRONT BUMPER RENTAINER RH	Sn Di 0.00	0.00	*31.20 F	4
22	1	39011390	*FRONT FENDER LH	R 0.00	0.00	*442.00 F	X
23	1	39011391	*FRONT FENDER RH	R 0.00	0.00	*442.00 F	X
24	1	13481997	*FRONT BUMPER FOG LAMP COVER LH	Sn 0.00	0.00	*180.70 F	X
25	1	13481998	*FRONT BUMPER FOG LAMP COVER RH	Sn 0.00	0.00	*180.70 F	X
26	1	39098907	*FRONT BUMPER FOG LAMP LH	Sn 0.00	0.00	*295.10 F	X
27	1	39098908	*FRONT BUMPER FOG LAMP RH	Sn 0.00	0.00	*295.10 F	X
28	1	39179270	*FRONT RADIATOR GRILLE SEAL RH 16.80	CM 0.00	0.00	*21.00 F	2
29	1	39179271	*FRONT RADIATOR GRILLE SEAL LH 16.80	CM 0.00	0.00	*21.00 F	2
30	1	39179263	*FRONT RADIATOR CENTER TOP SEAL 24.80	CM 0.00	0.00	*31.00 F	2
31	1	39015887	*FRT BUMPER SPONGE 150.40	CM 0.00	0.00	*188.00 F	2
32	1	39151027	*FRONT BUMPER REINFORCEMENT LOW (FIRBE)	Sn 0.00	0.00	*226.00 F	X
33	1	39160863	*FRONT BUMPER REINFORCEMENT UP (METAL) 483.20	R 0.00	0.00	*569.00 F	✓
34	1	39052086	*FRONT SUPPORT PANEL 205	Bu 0.00	0.00	*172.00 F	✓
35	1	39155356	*FRONT WASHING TANK	Sn 0.00	0.00	*91.00 F	X
36	1	39185893	*FRONT RADIATOR 676.80	R 0.00	0.00	*846.00 F	2
37	1	93160377	*FRONT RADIATOR COOLANT 48	Mc 0.00	0.00	*60.00 F	2
38	1	39013322	*FRONT RADIATOR FAN COWLING WITH MOTOR 1023.20	CM 0.00	0.00	*1,206.00 F	2
39	1	39011385	*FRONT AC CONDENSOR 680.40	R 0.00	0.00	*815.00 F	✓
40	1	39185909	*FRONT A.T.F COOLER 617.60	R 0.00	0.00	*610.00 F	2

F=Franchise part.

Sub Total (S\$)

12,808.80

+ Margin on L,N Items 10.00% (S\$)

1,280.88

Total Parts (S\$)

14,089.68

Munich Autocare Pte Ltd/SMU8691M/24/12/2022 12:41. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	10	FENDER INNER SHIELD CLIP LH
2	1	FRONT NUMBER PLATE WITH CASING
3	10	FRONT RADIATOR TOP GARNISH CLIPS

nn 70.00 X
B 35.00 ✓
M 70.00 ✓

Sub Total (\$\$) 175.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER , FENDER LH/RH , SUPPORT PANEL AND DAMAGE AREA	New	1,500.00	60d
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	120.00	20d
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00	
4	TO CONDUCT RE-PROGAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00	nn 7 X
5	TO CONDUCT 4 WHEEL ALIGNMENT AND BALANCING	New	120.00	nn X
6	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS AND DAMAGE AREA	New	350.00	60d
7	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , BONNET , BUMPER , FENDER LH/RH , SUPPORT PANEL AND DAMAGE AREA	New	1,200.00	800h

Gross Labour Cost (\$\$) 3,790.00

Munich Autocare Pte Ltd/SMU8691M/24/12/2022 12:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Feb 2023)
Parts: 144 OPEL ASTRA ST 1.6 D TURBO DIESEL (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Munich Autocare Pte Ltd/SMU8691M/07/02/2023 14:49
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39158021	*front headlamp cont unit LH	0.00	0.00	*569.00 F
2	1	39158021	*front headlamp cont unit RH	0.00	0.00	*569.00 F
Sub Total (S\$)						1,138.00
+ Margin on L,N Items 10.00% (S\$)						113.80
Total Parts (S\$)						1,251.80

F=Franchise part.

Munich Autocare Pte Ltd/SMU8691M/07/02/2023 14:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

✓ 455.2
✓ 455.2

ES FROM KCMC ASS. REC.

AIR DETAILS

Estimates on Parts

Franchise part.

Total Parts (S\$)	9,157.50
-------------------	----------

Munich Autocare Pte Ltd/SMU8691M/05/01/2023 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS