

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 28 Dec 2022

Preliminary Advice

Vehicle No	: SKW5737Z	Accident Date	: 22/12/2022
Make	: MERCEDES-BENZ C200	Policy No.	: DMPG22010314
Assignment Date	: 27/12/2022	Excess	: S\$200.00
Date of Inspection	: 27/12/2022	Est. Duration of Repair	: 4
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (HQ)		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,195.00
Revised Amount	:S\$	6,039.50
Check Items (Estimated)	:S\$	1,185.00
Total	:S\$	7,224.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	50,492.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,508.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Part by part repair, repairer unable to locate 2nd hand parts.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .