

FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22010314	Date of Loss:	22/12/2022
Vehicle Reg. No.:	SKW5737Z	Driveable?	
Driver Age/Info:	51 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JECS SINGAPORE PTE LTD		
Driver:	POH SIEW KHIM		
Make/Model:	MERCEDES-BENZ C200, 2.0 (A)	Vehicle Reg. Date:	16/08/2017
Vehicle Colour:	BLACK	Chassis No:	WDD2050422F334314
Engine No:	27492030608927		
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 04		
Description of Accident/Loss	REFER TO SAS		
Remarks:	VEHICLE IS IN W/SHOP.		
Present Location:	PLEASE ARRANGE VEHICLE SURVEY.		
	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

*Not with air
Penny B & pain
Ex & 200k*

COST OF CLAIMS	Amount
Parts	6,225.00
Miscellaneous Items	0.00
Labour	1,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	8,195.00
+ GST 7.00% (\$\$)	573.65
Nett Amount (\$\$)	8,768.65

This claim is handled by: ANDY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)
 Parts: 143 MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Falcon-Air Auto Services Pte Ltd/SKW5737Z/23/12/2022 16:51
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*RH Headlamp	0.00	0.00	CM *900.00 F	✓
2	1		*RH Headlamp Bracket	0.00	0.00	CM *140.00 F	✓
3	1		*Front Bumper	0.00	0.00	CM *1,100.00 F	✓
4	1		*Front Bumper Side	0.00	0.00	CM *60.00 F	✓
5	1		*Front Bumper Sponge	0.00	0.00	*140.00 F	?
6	1		*Front Bumper Carrier Lower	0.00	0.00	*120.00 F	?
7	1		*Front Bumper Carrier Top	0.00	0.00	*70.00 F	?
8	1		*RH Fog Garnish	0.00	0.00	mi *55.00 F	✓
9	1		*RH Front Bumper Side Retainer	0.00	0.00	CM *20.00 F	✓
10	1		*Front Console Mounting	0.00	0.00	*190.00 F	?
11	1		*Front Bumper Clip	0	0.00	na *80.00 FS	✓
12	1		*Front Parking Sensor Wire	0.00	0.00	*120.00 F	?
13	1		*Rivets	0	0.00	na *80.00 FS	✓
14	1		*RH Front Fender	0.00	0.00	B *640.00 F	✓
15	1		*RH Front Fender UnderShield (Front)	0.00	0.00	CM *140.00 F	✓
16	1		*RH Front Sports Rim AMG R19	0.00	0.00	na *900.00 F	✓
17	1		*RH Front Tyre	0	0.00	na *430.00 FS	70% ✓
18	1		*Front Grille Base	0.00	0.00	*100.00 F	?
19	1		*Front Air Duct	0.00	0.00	*110.00 F	?
20	1		*Bonnet Logo	0.00	0.00	na *65.00 F	x
21	1		*Front Fender Undershield Clip	0	0.00	na *80.00 FS	✓
22	1		*RH Front Parking Sensor Corner	0.00	0.00	na *180.00 F	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$) 5,720.00
 + Margin on L,N Items 10.00% (S\$) 505.00
 Total Parts (S\$) 6,225.00

Falcon-Air Auto Services Pte Ltd/SKW5737Z/23/12/2022 16:51. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	To check wiring and focus headlamp			201
2	To transfer tyre to new rim and balacing	New	50.00	
3	Computerise Wheel Alignment	New	50.00	201
4	To computer reset electronic functions	New	120.00	801
5	To straighten RH front inner panel, bonnet including replacement of parts	New	250.00	7
6	To spray paint on bonnet, RH front fender, front bumper	New	700.00	4501
		New	800.00	4001

Gross Labour Cost (\$\$)

1,970.00

Falcon-Air Auto Services Pte Ltd/SKW5737Z/23/12/2022 16:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110

Website: www.falconair.com.sg Email: email@falconair.com.sg