

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts: 143 MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SKW5737Z/23/12/2022 16:51
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH Headlamp	0.00	0.00	CM *900.00 F ✓
2	1		*RH Headlamp Bracket	0.00	0.00	CM *140.00 F ✓
3	1		*Front Bumper	0.00	0.00	CM *1,100.00 F ✓
4	1		*Front Bumper Side	0.00	0.00	CM *60.00 F ✓
5	1		*Front Bumper Sponge	0.00	0.00	*140.00 F ? ✓
6	1		*Front Bumper Carrier Lower	0.00	0.00	*120.00 F ? ✓
7	1		*Front Bumper Carrier Top	0.00	0.00	*70.00 F ? ✓
8	1		*RH Fog Garnish	0.00	0.00	mir *55.00 F ✓
9	1		*RH Front Bumper Side Retainer	0.00	0.00	CM *20.00 F ✓
10	1		*Front Console Mounting	0.00	0.00	*190.00 F ? ✓
11	1		*Front Bumper Clip	0	0.00	me *80.00 FS ✓
12	1		*Front Parking Sensor Wire	0.00	0.00	*120.00 F ?
13	1		*Rivets	0	0.00	me *80.00 FS ✓
14	1		*RH Front Fender	0.00	0.00	By *640.00 F ✓
15	1		*RH Front Fender UnderShield (Front)	0.00	0.00	CM *140.00 F ✓
16	1		*RH Front Sports Rim AMG R19	\$ 500.00	0.00 SN	me *900.00 F ✓
17	1		*RH Front Tyre	\$ 301.00	0 SN	me *430.00 FS 70% ✓
18	1		*Front Grille Base	0.00	0.00	*100.00 F ? ✓
19	1		*Front Air Duct	0.00	0.00	*110.00 F ? ✓
20	1		*Bonnet Logo	0.00	0.00	na *65.00 F X
21	1		*Front Fender Undershield Clip	0	0.00	me *80.00 FS ✓
22	1		*RH Front Parking Sensor Corner	0.00	0.00	me *180.00 F ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,720.00
+ Margin on L,N Items 10.00% (\$\$)	505.00
Total Parts (\$\$)	6,225.00

Falcon-Air Auto Services Pte Ltd/SKW5737Z/23/12/2022 16:51. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check wiring and focus headlamp	New	50.00
2	To transfer tyre to new rim and balacing	New	50.00
3	Computerise Wheel Alignment	New	120.00
4	To computer reset electronic functions	New	250.00
5	To straighten RH front inner panel, bonnet including replacement of parts	New	700.00
6	To spray paint on bonnet, RH front fender, front bumper	New	800.00
Gross Labour Cost (\$\$)			1,970.00

Falcon-Air Auto Services Pte Ltd/SKW5737Z/23/12/2022 16:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(A subsidiary of Falcon Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0830 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528340) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5655 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

PARTS: 3,965.00
+10% + 396.50
4,361.50
SN 961.00
LABOUR 1,100.00
6,422.50
LESS EXCESS - 200.00
6,222.50

HONG AUTO PARTS

Blk 10 Ang Mo Kio Industrial Park 2A #05-16
AMK AutoPoint S(568047)
Mobile: 9748 0604 9748 9630
Reg. No. 52980369-X GST Reg. No. 52-980369-X

M/S FALCON AIR AUTO SERVICES PTE LTD

TAX INVOICE

NO 16169

DATE 30/12/2022

SKW 5737Z (SUNMING)

TERMS:

Parts No	Description	Quantity	Unit Price	Amount
205 906 6802	RH headlamp	1		900.00
205 620 3501	RH headlamp bracket	1		140.00
205 880 0340	Front bumper	1		1100.00
205 885 0665	Front bumper side RH	1		60.00
205 885 0537	Front bumper sponge	1		140.00
205 885 1065	Front bumper carrier lower	1		120.00
205 885 1165	Front bumper carrier top	1		70.00
205 885 0823	Fog garnish RH	1		55.00
205 885 0921	Front bumper side retainer RH	1		20.00
205 620 4101	Front console mounting	1		190.00
E. & O. E.				
SUB-TOTAL				2795.00
GST 7%				195.65
TOTAL \$				2990.65

Goods Sold By: L

HONG AUTO PARTS

Blk 10 Ang Mo Kio Industrial Park 2A #05-16
AMK AutoPoint S(568047)
Mobile: 9748 0604 9748 9630
Reg. No. 52980369-X GST Reg. No. 52-980369-X

M/S FALCON AIR AUTO SERVICES PTE LTD

TAX INVOICE

NO 16170

DATE 30/12/2022

SKW 5737Z (SUNMING)

TERMS:

Parts No	Description	Quantity	Unit Price	Amount
000 905 5604	Front parking sensor RH corner	1		180.00
205 880 0218	RH front fender	1		640.00
205 690 3201	RH front fender undershield (front)	1		140.00
205 888 0023	Front grille base	1		100.00
205 505 1830	Front air duct	1		110.00
E. & O. E.				
SUB-TOTAL				1170.00
GST 7%				81.90
TOTAL \$				1251.90

Goods Sold By: L