

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vonn Siow Lie Mien

Date: 28 Dec 2022

Preliminary Advice

Vehicle No	: SDG1600C	Accident Date	: 14/12/2022
Make	: MERCEDES-BENZ E250	Policy No.	: 1001927715
Assignment Date	: 27/12/2022	Excess	: S\$700.00
Date of Inspection	: 27/12/2022	Est. Duration of Repair	: 6
Inspection At	: ELITE AM PTE. LTD.		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,981.74
Revised Amount	:S\$	7,921.56
Check Items (Estimated)	:S\$	1,895.01
Total	:S\$	9,816.57

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	40,320.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,680.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- () The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .