

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SDG1600C

Vehicle Model : MERCEDES E250

Chassis Number : WDD2120362A909313

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	FRONT LHS RIM / <i>cut</i>	1	\$ 988.72 ✓
2	FRONT LHS FENDER / <i>Paint</i>	1	\$ 1140.53 ✓
3	FRONT LHS DOOR / <i>BT</i>	1	\$ 1902.73 ✓
4	LHS SIDE SKIRT / <i>cut</i>	1	\$ 770.01 ✓
5	FRONT LHS DOOR WINDOW OUTER CHROME MOULDING ?	1 <i>nn</i>	\$ 132.24 ✗
6	FRONT LHS DOOR WINDOW TOP RUBBERSTRIP ?	1 <i>nn</i>	\$ 304.27 ✗
7	FRONT LHS DOOR WEATHERSTRIP ? <i>nec</i>	1	\$ 317.05 ✓
8	REAR LHS DOOR X <i>Repair</i>	1	\$ 1956.17 ✗
9	REAR LHS DOOR WEATHERSTRIP ? <i>nn</i>	1	\$ 317.05 ✗
10	REAR LHS DOOR WINDOW OUTER CHROME MOULDING ?	1 <i>nn</i>	\$ 160.14 ✗
11	REAR LHS DOOR WINDOW OUTER TOP RUBBERSTRIP ?	1 <i>nn</i>	\$ 469.26 ✗
12	REAR LHS FENDER X <i>Repair</i>	1	\$ 2554.23 ✗
13	REAR LHS RIM X <i>nn</i>	1	\$ 968.72 ✗
14	LHS SIDE MIRROR / <i>Dis</i>	1	\$ 1090.37 ✓
15	LHS SIDE MIRROR COVER / <i>CRA</i>	1	\$ 406.54 ✓
16	LHS SIDE MIRROR GLASS / <i>CRA</i>	1	\$ 292.22 ✓

	\$ 13770.25
Discount Less 5%	\$ 688.51
List Prices Total	13,081.74

6908.17
-10%
6217.35

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SDG1600C

Vehicle Model : MERCEDES E250

Chassis Number : WDD2120362A909313

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL LHS BODY ATTACHMENTS & FITTINGS TO ENABLE REPAIRS: TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 600
2	TO SPRAY PAINTING ON: LHS FRONT FENDER, LHS FRONT DOOR, REAR LHS DOOR, REAR LHS FENDER, LHS SIDE SKIRT.	\$ 1500.00 1000
3	WHEEL ALIGNMENT	\$ 120.00 60
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00 ? 150

Labour Total \$ 3900.00 1810

Parts & Labour Total \$ 16981.74

6 Days.

Insurance repair

After repair photos.

Gene Qiaf

82880282

27/12/22

8027.35 + 60 (supp)

L/S - 6469.88
= 6450

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Authenticated by Repairer Signature: Date:
