

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s ELITE AUTO

of

Insured:

Policy No. 1001927715

Claims No. 294970

Sum Insured: Excess: \$700

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S

Bal. or Market Value: \$56k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / ☒ REV / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDG1600C

Yr Regn: 28 Feb/2014

Type ☒ M.Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ E250 c.c. 1991

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 191748

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2120362A909313 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ norder / Jammed / Leaked / Burnt orBrake: ☒ norder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/R or

Tyre Size: F: 245/40R18

R: //

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/12/2022

D.O.I. 27-12-2022

Survey held at W/S 2:30PM

Des. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop orThe ☒ U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/2/23 Lump Sum \$6450 confirmed by email (red 10,931.74, 62%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 3/2/23-typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3 + RS. SI

Photos

Other:

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Wash and

Report Filed: Merimen

Lump Sum / REP: LS \$6450