



Section A - Accident Details

Registration Number	SHD6270G
Case Reference Number	TAX/12/22/2067
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHAN LYE HUAT(ZENG LAIFA)
Type of Accident	Head to Rear
Accident Date and Time	23/12/2022 12:20 AM
Accident Reported Date and Time	23/12/2022 3:49 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117232
Special Instruction to ARC,if any	TP/ REAR PORTION /III
Prepared Date and Time	27/12/2022 1:28 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$1,703.47	\$648.12
Total Other Cost	\$340.00	\$40.00
TOTAL COST	\$3,119.47	\$1,088.12
Lump Sum Total	\$3,100.00	\$1,100.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang (LKK) / III
ARC / Surveyor Sign Off Date	27/12/2022 4:44 PM	27/12/2022 4:36 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quoqiang (LKK) & Email :quoqiang@lkkauto.com HP:82880282	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2301-0301	Invoice Number	
Quotation Date	20.01.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$0.00	\$0.00
Total Other Costs	\$340.00	\$40.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$12.00	25.00	\$18.00	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	Replace
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	Replace
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$992.30	0.00	\$0.00	Replace	Not Given
		75441-47220	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	0.00	\$59.10	0.00	\$0.00	Replace	Not Given
		75442-47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$59.10	0.00	\$0.00	Replace	Not Given
			STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given

√ dd
√ nec
√ nec
√ nec
√ nec
√ nec
X
√ nec
√ cut
√ nec
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/02/2023

User ID : PohSuan

			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given
Total					\$2,729.20		\$810.15		

X

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	810.15	
	-20%	
	648.12	L/S \$1,100/-
+	200.00	
+	240.00	
	1,088.12	