



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CC4/ASM22012880/Apa3q2

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

Date: 10/05/2023

ATTN:VALE OH

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8440A	Veh. Inspected	SJR 635E
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04H31	Excess (\$)	0.00
Assign From		Assign Date	27/12/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2040452A267768	Colour	BLACK
Odometer	253746 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	6 mm
L/H Front Tyre	225/45 R17	PIRELLI	6 mm
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/12/2022	Inspection Date	28/12/2022
Survey held at	LC AUTOMOTIVE BLOCK 10 SIN MING IND.ESTATE , SECTOR C #01-20 SINGAPORE 575645		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**