

# LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and final approval from Insurance Company

Acknowledged by Repairer

Signature: 28<sup>th</sup> DEC 2023

Date:

WEE POH CHAN PHYLLIS  
Blk 25 Kaki Bukit Road 4  
# 05-26 SYNERGY @KB  
Singapore 417800

TRAYA.  
Xiao Tong

Accident date: 25<sup>th</sup> DEC 2022

Estimated repair cost for vehicle no: SJR635E MERCEDES C180 '2009 (COE TIL 31.5.2024)

| S/n | Qty | Items/Nett                                      | U/price | Amount         |
|-----|-----|---|---------|----------------|
| 1   | 1   | Rear fender RH <i>Repair</i>                    |         | \$1,954.00 X   |
| 2   | 1   | Rear fender R/H cowling <i>Not Nec</i>          |         | \$215.00 X     |
| 3   | 1   | Front R/H door <i>Dented</i>                    |         | \$1,855.20 ✓   |
| 4   | 1   | Front R/H door top hinges <i>3 NP</i>           |         | \$155.20 X     |
| 5   | 1   | Front R/H door lower hinges <i>1 NP</i>         |         | \$155.20 X     |
| 6   | 1   | Front RH door exp rivet set <i>1 Nec</i>        |         | \$75.00 X      |
| 7   | 1   | door side skirt <i>Torn</i>                     |         | \$788.00 ✓     |
| 8   | 1   | Front side mirror -RH <i>3 NP</i>               |         | \$685.20 X     |
| 9   | 1   | Front side mirror cover -RH <i>1 Nec</i>        |         | \$185.20 X     |
| 10  | 1   | Front RH door inner lock <i>Damaged</i>         |         | \$590.00 +50   |
| 11  | 1   | front R/H door top moulding <i>Not Nec</i>      |         | \$211.30 X     |
| 12  | 1   | Front RH door gear motor assy <i>Damaged</i>    |         | \$852.00 385   |
| 13  | 1   | front R/H door outer handle <i>Not Nec</i>      | 7805.60 | \$188.20 X     |
| 14  | 1   | front R/H door glass rubber <i>3 NP</i>         |         | \$210.00 X     |
| 15  | 1   | front R/H door top moulding rubber <i>1 NP</i>  |         | \$185.30 X     |
| 16  | 1   | Front R/H door inner rubber <i>Nec</i>          | 7025.04 | \$218.20 ✓     |
| 17  | 1   | Front RH door lower protector chrome <i>Nec</i> |         | \$285.20 ✓ 105 |
| 18  | 1   | front R/H door inner trim board <i>cracked</i>  |         | \$1,480.00 850 |
| 19  | 1   | Rear RH door <i>Dented</i>                      |         | \$1,954.00 ✓   |
| 20  | 1   | rear RH outer handle <i>3 NP</i>                |         | \$185.20 X     |
| 21  | 1   | rear RH door top moulding <i>1 Nec</i>          |         | \$211.00 X     |
| 22  | 1   | rear RH door inner rubber <i>Nec</i>            |         | \$215.20 ✓     |
| 23  | 1   | rear RH door inner lock <i>3 NP</i>             |         | \$590.00 X     |
| 24  | 1   | rear RH door gear motor assy <i>1 NP</i>        |         | \$852.00 X     |
| 25  | 1   | rear R/H door glass rubber <i>1 Nec</i>         |         | \$210.00 X     |
| 26  | 1   | rear R/H door top moulding rubber <i>3 NP</i>   |         | \$185.30 X     |
| 27  | 1   | rear R/H door top hinges <i>1 Nec</i>           |         | \$155.20 X     |
| 28  | 1   | rear R/H door lower hinges <i>1 Nec</i>         |         | \$155.20 X     |
| 29  | 1   | rear RH door lower protector chrome <i>Nec</i>  |         | \$285.20 105   |
| 30  | 1   | Rear R/H door inner trim board <i>Damaged</i>   |         | \$1,480.00 850 |

Subtotal :- \$16,766.50

Labour charges

To remove & re-fix cushion

\$150.00 120

tuff Kote

1560 \$150.00 40

to remove & Refix rear petrol tank

total: 8585.04 \$180.00 X

Spray painting

1/5: 6.8K \$1,000.00 800

Panel beating

05 Days \$1,000.00 600

Subtotal :- \$2,480.00

Total :- \$19,246.50