

ASS. REC. BY:

REF:

TJ / 22012882/kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$190k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNF 72105Yr Regn: 06, 22Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy AITISc.c. 1798Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 32674

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR 288 3BE 600009397Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 225/45R17BS: PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 4 mmL/Bal. 4 mmL/Bal. 4 mmD.O.A. 10/12/22D.O.I. 30/12/2022

Survey held at _____

Des. of Damages: Nil / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Got B2

27/2 / 1 Sy @ 3000 C.L.R.

\$2400.00

Re offer workshop

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Not Notion
L1 Rep 83000/r
Refining the team
98910663
4 days

Estimation

Date: 30/12/2022

Vehicle: SNF7210S

Make / Model: TOYOTA ALTIS

INS: INDIA

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	SIDE MIRROR <i>Per</i>	1	\$ 685.00	\$ 685.00
2	FRONT FENDER LH <i>Per</i>	1	\$ 698.00	\$ 698.00
3	FRONT FENDER COWLING LH <i>Per</i>	1	\$ 159.00	\$ 159.00
4	FRONT FENDER EMBLEM 'HYBRID' <i>Per</i>	1	\$ 62.00	\$ 62.00
5	FRONT DOOR LH <i>1150 Per</i>	1	\$ 1,398.00	\$ 1,398.00
6	FRONT DOOR HINGES LOWER LH <i>R</i>	1	\$ 68.00	\$ 68.00
7	FRONT DOOR WEATHERSTRIPE LH <i>Per</i>	1	\$ 251.00	\$ 251.00
8	FRONT DOOR INNER TRIM BOARD LH <i>Per</i>	1	\$ 512.00	\$ 512.00
9	FRONT DOOR PILLAR LH <i>R</i>	1	\$ 522.00	\$ 522.00
10	SIDE SKIRTING LH <i>My car</i>	1	\$ 798.00	\$ 798.00
TOTAL PART				\$ 5,153.00
LIST DOWN				25%
AFTER LIST DOWN				\$ 1,288.25
SPECIAL NETT				\$ 3,864.75
1	FRT FENDER INNERSHIELD CLIP SET LH <i>an</i>	1	\$ 50.00	\$ 50.00
2	FRT FENDER QUARTER GLASS SEALANT LH <i>an</i>	1	\$ 80.00	\$ 80.00
3	FRONT DOOR INNER TRIM CLIPS <i>an</i>	1	\$ 50.00	\$ 50.00
TOTAL AMOUNT				\$ 180.00
LABOUR				
1	CHECK WIRING	1	\$ 100.00	\$ 100.00
2	R+R FRONT DOOR MECHANISM	1	\$ 200.00	\$ 200.00
3	WHEEL ALIGNMENT <i>an</i>	1	\$ 120.00	\$ 120.00
4	R+R FRT FENDER QUARTER GLASS LH	1	\$ 120.00	\$ 120.00
5	RESET TROUBLE CODE <i>an</i>	1	\$ 200.00	\$ 200.00
6	KNOCK	1	\$ 500.00	\$ 500.00
7	SPRAY	1	\$ 500.00	\$ 500.00
TOTAL AMOUNT				\$ 1,740.00
Parts Replacement Amount				\$ 3,653.25
Total Amount for Labour				\$ 2,040.00
Total Amount				\$ 5,693.25

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged parts (A) for confirmation
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Witnessed by Repairer

Signature

Date