

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27/22/2022

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1503 T

1 pc	Front bumper	Scr	\$	811.11	/
1 pc	Front n/s head lamp	?	\$	1,531.57	XIVN
2 pcs	Front bumper n/s & o/s side bracket @ \$32.51	BR	\$	65.02	132.51 /
1 pc	Front n/s fender	Dent	\$	514.02	/
1 pc	Front n/s fender inner shield	XIVN	\$	476.72	
1 pc	Front n/s rim	Scr x R	\$	246.00	xR
			\$	3,344.44	1357.04
			\$	668.89	271.60
			\$	2,675.55	1081.04
			\$	48.00	NEL
			\$	28.00	XIVN
			\$	30.00	NEL
			\$	50.00	XIVN
			\$	80.00	/
			\$	180.00	XIVN
			\$	650.00	400
			\$	600.00	400
			\$	120.00	XIVN
			\$	4,461.55	2039.04

KK Auto Consultants

Repairer of the following

Survey before/after

display damaged parts

prices are subject to

Third party survey is on a

No illegal modifications

Supplementary items

is subject to final

Acknowledged by

Signature:

Less 20%