

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22012884/RPA3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0010208
Claimant Vehicle No : SJJ4428C **Insured Vehicle No :** SNH7764A
 Date of Loss: 22/12/2022 Nature of Claim: TP Claim No: MPC2022D0012179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ4428C**
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2421504A
 Reg. Date: 30/05/2017 (Man. Year: 2017) Chassis No: SJNFEAJ11U1951279
 Colour: Grey Odometer: 117710 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,017.58	13,474.76	1,542.82	10.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,783.00	5,133.00	2,650.00	34.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	22,800.58	18,607.76	4,192.82	18.39
+ GST 8.00/8.00% (\$\$)	1,824.05	1,488.62	335.43	18.39
Nett Amount (\$\$)	24,624.63	20,096.38	4,528.25	18.39
+ Car Rental (12.0 x S\$90.00/day + 8.00% GST) (\$\$)		1,166.40		
Nett Liability (\$\$)		21,262.78		

INSPECTION

Date of Assignment: 23/12/2022
 Date Inspected: 27/12/2022 Inspected At: TC AutoClinic Pte Ltd (Leng Kee)
 25 Leng Kee Road
 Singapore 159097
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ4428C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLINING ASSY	Deformed	1,426.80 FN	*1,426.80 FN
2	1		*WSTRIP ASSY -RR LH	Necessary	181.90 FN	*181.90 FN
3	1		*HINGE UPPER LH RR UPPER	Not Necessary	63.50 FN	*- FN
4	1		*HUNGE ASSY LOWER LH RR	Bent	42.40 FN	*42.40 FN
5	1		*MLDG RR DOOR OUTER GLASS	Necessary	237.80 FN	*237.80 FN
6	1		*TAPE -RR DOOR ,LH	Necessary	35.00 FN	*35.00 FN
7	1		*TAPE -RR DOOR ,LH	Necessary	35.00 FN	*35.00 FN
8	1		*MOULDING SASH RR LH	Not Necessary	115.20 FN	*- FN
9	1		*DOOR -REAR LH	Buckled	1,258.20 FN	*1,258.20 FN
10	1		*FENDER OVER GARNISH RR LH	Scratched	584.20 FN	*584.20 FN
11	1		*PLATE KICKING GARNISH RR LH	Not Necessary	53.90 FN	*- FN
12	1		*WELT BODY SIDE LH REAR	Not Necessary	223.30 FN	*- FN
13	1		*MOULDING RR LH DOOR OUTER LOWER	Deformed	303.00 FN	*303.00 FN
14	1		*MOULDING FRT LH DOOR OUTER LOWER	Not Necessary	370.20 FN	*- FN
15	1		*SILL -OTR LH	Bent	1,318.80 FN	*1,318.80 FN
16	1		*WHEEL -ROAD AL	Cut	1,332.70 FS	*1,332.70 FS
17	1		*BEAM REAR ASSY	Bent	1,426.70 FS	*1,426.70 FS
18	1		*ABSORBER -SHOCK RR LH	Bent	199.30 FS	*199.30 FS
19	1		*HUB REAR WHEEL	Deformed	363.90 FS	*363.90 FS
20	1		*BELT ASSY -LH FRT PASSENGER	Activated	788.50 FS	*788.50 FS
21	1		*BELT ASSY -FRR RH DRIVER	Not Necessary	788.50 FS	*- FS
22	1		*SENSOR SIDE A/BAG MODULE	Activated	1,560.60 FS	*1,560.60 FS
23	1		*GARNISH CENTER PILLAR UPPER LH	Not Necessary	58.40 FN	*- FN
24	1		*GARNISH CENTER PILLAR UPPER RH	Not Necessary	58.40 FN	*- FN
25	1		*SEN-SIDE AIR ,RH	Activated	367.20 FS	*367.20 FS
26	1		*MODULE SIDE ,LH FRT SEAT AIR BAG	Activated	1,162.10 FN	*1,162.10 FN
27	1		*LH CURTAIN AIRBAG	Activated	1,866.50 FN	*1,866.50 FN
28	1		*SENSOR -AIR BAG	Activated	674.50 FS	*674.50 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	16,896.50	15,165.10
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	1,878.92	1,690.34
Total Parts (\$\$)	15,017.58	13,474.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS,INTERROGATION & REPROGRAM MODULE WITH CONSULT	New	240.00	240.00
2	PERFORM NISSAN COMPUTERISED DIAGNOSIS ALIGN VEH LEVER ,CALIBRATION SENSOR AND ROAD TEST	New	270.00	270.00
3	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	240.00	240.00
4	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	300.00	200.00
5	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION -PASSENGER	New	95.00	95.00
6	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/SHORT CIRCUIT ,REPAIR WHEN NECESSARY	New	240.00	0.00
7	REPAIR /REPLACE FRT LH DOOR ,RR LH DOOR ,LH ROCKER PANEL,3 PILLAR & LH REAR FENDER	New	2,340.00	780.00
8	RESPRAY FRT LH DOOR ,RR LH DOOR ,RR LH FENDER ,LH SILL & 3 PILLAR	New	1,250.00	500.00
9	TRANSFER RR LH DOOR MECHANISM TO NEW DOOR	New	120.00	120.00
10	REMOVE/REFIX ROOF LINING SIDE PANEL GARNISH ,SEATS & CUSHION TO FACILITATE REPAIR	New	735.00	735.00
11	REMOVE /REFIX /REPLACE REAR UNDERCARRIAGE ASSY TO FACILITATE REPAIR	New	960.00	960.00
12	REMOVE/REFIX /REPLACE REAR LH TYRE /RIM	New	48.00	48.00
13	REMOVE/REFIX SRS AIRBAGS & MODULE	New	245.00	245.00
14	REMOVE/REWRAP FRT LH PASSENGER SEAT LEATHER TO FACILITATE REPLACEMENT OF AIRBAG	New	450.00	450.00
15	REPLACE 1 PC TYRE REAR LH 215/60 R17	New	250.00	250.00
Gross Labour Cost (\$\$)			7,783.00	5,133.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >