

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 173/IC/TCAC/SAY/2022
DATE : 23-DEC-2022

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : POH LEONG CHEW
ADDRESS : 170 BEDOK SOUTH ROAD
#10-352
S(460170)
TELEPHONE NO : 90622602

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : D22MTPV01007504
VEHICLE NO : SJJ4428C
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2421504A
CHASSIS NO : SJNFEAJ11U1951279
MILEAGE : 117736 KM
DATE IN : 23/12/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 22/12/2022

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJJ4428C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 COKI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	240.00
2 IBS	PERFORM NISSAN COMPUTERISED DIAGNOSIS, ALIGN VEH LEVEL, CALIBRATION SENSOR AND ROAD TEST	270.00	270.00
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	240.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	200.00
5 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	95.00	95.00
6 WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	.00
7 ZZ/001	CONDUCT 3RD PARTY CLAIM III DATE:22/12/2022 TIME:1810 LOCATION:JUNC OF EUNOS RD 5 & AVE 3		
8 ZZ/002	REPAIR/REPLACE FRT LH DOOR, RR LH DOOR, LH ROCKER PANEL, B PILLAR & LH REAR FENDER	2340.00	780.00
9 ZZ/003	RESPRAY FRT LH DOOR, RR LH DOOR, RR LH FENDER, LH SILL & B PILLAR	1250.00	500.00
10 ZZ/004	TRANSFER RR LH DOOR MECHANISM TO NEW DOOR	120.00	120.00
11 ZZ/005	REMOVE/REFIX ROOF LINING, SIDE PANEL GARNISH, SEATS & CUSHION TO FACILITAE REPAIR	735.00	735.00
12 ZZ/006	REMOVE/REFIX/REPLACE REAR UNDERCARRIAGE ASSY TO FACILITATE REPAIR	960.00	960.00
13 ZZ/007	REMOVE/REFIX/REPLACE REAR LH TYRE/RIM	48.00	48.00
14 ZZ/008	REMOVE/REFIX SRS AIRBAGS & MODULE	245.00	245.00
15 ZZ/009	QC & CONSULT CHECK		
16 ZZ/011	REMOVE/REWRAP FRT LH PASSENGER SEAT LEATHER TO FACILITATE REPLACEMENT OF AIRBAG	450.00	450.00
17 ZZ/012	REPLACE 1 PC TYRE REAR LH 215/60/R17 (SUPP)	250.00	250.00
18 ZZ/10	CARWASH & VACUUM		

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJJ4428C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
		TOTAL LABOUR CHARGES	7783.00	5133.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJJ4428C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SEN-SIDE AIR,RH (SUPP)	K8830-3RA0A			367.20	OK
2	LH CURTAIN AIRBAG (SUPP)	985P1-4EA0A	1866.50			OK
3	MODULE SIDE,LH FRT SEAT AIR BAG (SUPP)	985H1-4EA0A	1162.10			OK
4	GARNISH CENTER PILLAR UPPER RH (SUPP)	76913-4EA2A	58.40			OK
5	GARNISH CENTER PILLAR UPPER LH (SUPP)	76914-4EA2A	58.40			OK
6	SENSOR-AIR BAG (SUPP)	K8581-3RA0A			674.50	OK
7	WHEEL-ROAD AL	D0300-4EA1A			1332.70	OK
8	BEAM REAR ASSY (SUPP)	55501-4EA0A			1426.70	OK
9	ABSORBER-SHOCK RR LH (SUPP)	E6210-4EA2C			199.30	OK
10	HUB REAR WHEEL (SUPP)	43202-4EA0A			363.90	OK
11	HEADLINING ASSY	73910-4EA1A	1426.80			OK
12	BELT ASSY-LH FRT PASSENGER	86885-4EA2A			788.50	OK
13	BELT ASSY-FRR RH DRIVER	86884-4EA2A			788.50	X
14	SENSOR SIDE A/BAG MODULE	K8820-4EH0D			1560.60	OK
15	WSTRIP ASSY-RR LH	82831-4EA0A	181.90			OK
16	HINGE UPPER LH RR UPPER	82401-4EA0A	63.50			X
17	HINGE ASSY LOWER LH RR (SUPP)	82421-4EA0A	42.40			X
18	MLDG RR DOOR OUTER GLASS	82821-4EA0A	237.80			OK
19	TAPE-RR DOOR,LH	82819-4EA0A	35.00			OK
20	TAPE-RR DOOR,LH	82813-4EA0A	35.00			OK
21	MOULDING SASH RR LH	82283-4EA1C	115.20			X
22	DOOR-REAR LH	H2101-HV0MA	1258.20			OK
23	FENDER OVER GARNISH RR LH	93829-4EA0A	584.20			OK
24	PLATE KICKING GARNISH RR LH	769B7-4EA0A	53.90			X
25	WELT BODY SIDE LH REAR	76924-4EA0A	223.30			X

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJJ4428C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	MOULDING RR LH DOOR OUTER LOWER	82871-4EA0A	303.00			OK
27	MOULDING FRT LH DOOR OUTER LOWER	80871-4EA0A	370.20			X
28	SILL-OTR LH	65415-4EAMA	1318.80			OK
SUB TOTAL			8526.10	0.00	6713.40	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1705.22	0.00	0.00	
GRAND TOTAL			6820.88	0.00	6713.40	
OVERALL TOTAL			13534.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJJ4428C

NETT ITEM 8526.10
LESS 20.00%) -1705.22
NETT AMOUNT 6820.88

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 6713.40
LESS .00%) 0.00
SPECIAL NETT AMOUNT 6713.40

TOTAL LABOUR CHARGES 5133.00
TOTAL SPARE PARTS CHARGES 13534.28

TOTAL CHARGES 18667.28
ADD 8 % GST 1493.38

GRAND TOTAL 20160.66
