



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

Send Adrian
14.02.2023

專業服務：汽車意外保險賠償·拖車·汽車修理及維修服務·打嗎呷·噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting

Attn: The Motor Claims Department

Date 30/12/2023

Your Insured Vehicle - **SJW 1181 P**

Allianz SE, Singapore Branch

79 Robinson Road, #09-01

Asia Square Tower 1

Singapore 068897

LKK Auto Consultants hence notify the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TP Allianz
Xiao Tony

Dear Sir,

Estimated Cost of repair for Vehicle No. **ES 3223 U And SJW 1181 P** on **24/12/2022 at 09:00am.**

Signature:

Date:

To Supply:-

Nett Item:

1pc	Front head lamp RH <i>cut</i>		\$3,030.00	✓
1pc	Front fender RH <i>Repair</i>		\$ 700.00	X
1pc	Front fender cowlding RH <i>Deband</i>		\$ 208.00	✓
1pc	Front bumper <i>Distorted</i>		\$1,400.00	✓
1pc	Front bumper bracket <i>cut</i>		\$ 180.00	✓
1pc	Front bumper side retainer RH <i>band</i>		\$ 40.00	✓
4pcs	Front bumper sensor <i>1 piece band</i>	\$ 280.00	\$1,120.00	280
1pc	Front bumper under cover <i>XRE M</i>		\$ 340.00	+
1pc	Front sport rim RH <i>cut</i>		\$1,100.00	✓
1pc	Front head lamp low beacket <i>XRE M</i>		\$ 30.00	X
			\$8,148.00	
		Less	10%	\$ 814.80
				\$7,333.20

6238

5614.20

To dismanlte & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affecte portion.

Computer Wheel Alignment

To check wiring functions.

\$ 520.00 *400*

\$ 680.00 *400*

\$ 120.00 *80*

\$ 80.00 *30*

\$8,733.20



Total: 6524.20

CP/P2

Adrian King

PIP 30/12/22

04 Days.