

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/GRB22012887/UYA3Q2  
**Date:** 17/04/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01  
**Claimant Vehicle No :** SME8836Y **Insured Vehicle No :** SLW2289H  
 Date of Loss: 25/12/2022 Nature of Claim: TP Claim No: MFL2022D0012022

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SME8836Y**  
 Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FGJH709484  
 Reg. Date: 22/10/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5019897  
 Colour: Pearl White Odometer: 42064 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm  
 Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	700.00	680.00	49.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,380.00</b>	<b>700.00</b>	<b>680.00</b>	<b>49.28</b>
<b>+ GST 8.00/8.00% (S\$)</b>	110.40	56.00	54.40	49.28
<b>Nett Amount (S\$)</b>	<b>1,490.40</b>	<b>756.00</b>	<b>734.40</b>	<b>49.28</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (S\$)</b>		120.00		
<b>+ Doc/Search Fee (S\$)</b>		26.75		
<b>Nett Liability (S\$)</b>		<b>902.75</b>		

**INSPECTION**

Date of Assignment: 10/01/2023  
 Date Inspected: 10/01/2023 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)  
 2008/2010/2012  
 Singapore 489977  
 Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
<b>Parts:</b> 143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SME8836Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH (NPA)	Repair	0.00 FS	*- FS
2	1		*REAR DOOR LH (NPA)	Repair	0.00 FS	*- FS
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	500.00
3	ANTI-RUST COATING	New	80.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >