



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TP Allianz
Xiao Tony

NG PENG HENG

BLK 239 LORONG 1 TOA PAYOH #08-94

SINGAPORE 310239

TAX INVOICE

Repair Code : CLM17535

Date in : 23/12/2022

Vehicle Num. : SMP5707Z

Model : HONDA SHUTTLE 1.5G CVT SENSING

Chassis/Eng# : GK82100597/L15B6020715

Contact : 96711205

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE CARRIAGE <i>Bent</i>	1	1555.00	✓ 1,555.00
REAR BUMPER <i>Reps torn</i>	1	1350.60	950 1,350.60
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	26.50	+ 53.00
REAR RH DOOR <i>Distorted</i>	1	879.50	✓ 879.50
REAR RH DOOR BLACK TAPE <i>new</i>	1	55.80	✓ 55.80
REAR RH DOOR CHECKER <i>new</i>	1	48.00	+ 48.00
REAR RH DOOR GLASS CHANNEL BRACKET <i>Bent</i>	1	34.20	✓ 34.20
REAR RH DOOR GLASS CHANNEL WEATHER STRIP <i>new</i>	1	165.00	+ 165.00
REAR RH DOOR GLASS OUTER MOULDING <i>new</i>	1	85.60	+ 85.60
REAR RH DOOR GLASS REGULATOR WITH MOTOR <i>Bent</i>	1	295.50	✓ 295.50
REAR RH DOOR HINGE (BOTTOM) <i>Bent</i>	1	45.00	✓ 45.00
REAR RH DOOR HINGE (TOP) <i>new</i>	1	45.00	+ 45.00
REAR RH DOOR INNER RUBBER STOPPER L/R <i>new</i>	2	18.50	+ 37.00
REAR RH DOOR INNER TRIM BOARD <i>cracked</i>	1	569.30	✓ 569.30
REAR RH DOOR MECHANISM LOCK <i>Damaged</i>	1	231.00	✓ 231.00
REAR RH DOOR OUTER FRAME GARNISH <i>new</i>	1	33.10	✓ 33.10
REAR RH DOOR WEATHER STRIP <i>new</i>	1	78.00	✓ 78.00
REAR RH DOOR WEATHER STRIP (LOWER) <i>new</i>	1	48.00	+ 48.00

*** This is a computer-generated document which requires no signature.***

Yaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG PENG HENG
BLK 239 LORONG 1 TOA PAYOH #08-94
SINGAPORE 310239

Contact : 96711205

TAX INVOICE

Repair Code : CLM17535

Date in : 23/12/2022

Vehicle Num. : SMP5707Z

Model : HONDA SHUTTLE 1.5G CVT SENSING

Chassis/Eng# : GK82100597/L15B6020715

REAR RH DOOR WEATHER STRIP (VERTICAL) <i>new</i>	1	65.00	+	65.00
REAR RH FENDER <i>Repair</i>	1	1238.90	+	1,238.90
REAR RH FENDER GLASS MOULDING ASSY <i>new</i>	1	478.10	+	478.10
REAR RH FENDER INNER SHIELD COVER <i>new</i>	1	83.70	+	83.70
REAR RH SHOCK ABSORBER <i>new</i>	1	374.20	+	374.20
REAR RH WHEEL BEARING <i>new</i> <i>5656.10</i>	1	415.00	✓	415.00
REAR RH WHEEL CAP <i>new</i> <i>4524.88</i>	1	130.00	✓	130.00
RH ROCKER GARNISH <i>Deland</i>	1	417.80	✓	417.80

Subtotal before discount

8,811.30

Percentage discount 20%

1,762.26

Sub-total 1

7,049.04

REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30.00	50.00
REAR RH DOOR INNER SPEAKER <i>new</i>	1	150.00	100.00	150.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	30.00	50.00
REAR RH FENDER GLASS SEALANT <i>new</i>	1	40.00	30.00	40.00
REAR RH FENDER INNER SHIELD COVER CLIPS - SET <i>new</i>	1	30.00	+	30.00
REAR RH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	+	50.00
REAR RH FENDER SEALANT <i>new</i>	1	80.00	60.00	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG PENG HENG
BLK 239 LORONG 1 TOA PAYOH #08-94
SINGAPORE 310239

Contact : 96711205

TAX INVOICE

Repair Code : CLM17535

Date in : 23/12/2022

Vehicle Num. : SMP5707Z

Model : HONDA SHUTTLE 1.5G CVT SENSING

Chassis/Eng# : GK82100597/L15B6020715

REAR RH TYRE <i>new</i>	1	280.00	<i>+</i> 280.00
REAR RH WHEEL RIM <i>new</i>	1	250.00	<i>+</i> 250.00
RH ROCKER GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>30</i> 50.00
Subtotal before discount			1,030.00
Percentage discount 0%			0.00
Sub-total 2			1,030.00
Parts-total			8,079.04

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall fender glass

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

4,130.00

12,209.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 3

Adrian Lj
h/s 27/12/22
whl: 7054.88 07 Pays.
h/s: 5.6k.