

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH8082T
 MAKE REG 07.10.2016
 MODEL TOYOTA PRIUS G4

DATE 03.10.2022
 CHIANGINCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$503.04
1	REAR BUMPER LOWER COVER			\$654.96
1	REAR BUMPER REINFORCEMENT			\$378.32
1	REAR BUMPER TOW COVER			\$82.70
10	REAR BUMPER CLIP			\$22.00
	SUB TOTAL		1262.70	\$1,641.02
	25.00%		947.02	\$410.26
	DISCOUNTED TOTAL			\$1,230.77
1	REAR BUMPER MAT		50	\$50.00
1	BUMPER REVERSE SENSOR		135.70	\$135.70
			10% - 122.13	\$167.13
	Labour Charge			
	Panel Beating		350	\$550.00
	Spray Painting Charge		250	\$300.00
	Check Wiring & Lighting		630	\$60.00
	Remove/Refix Reverse Sensor		30	\$60.00
	TOTAL LABOUR			\$970.00
	ESTIMATE TOTAL		1749.15	\$2,367.90
			45\$1400	
			02 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 WP 4/10/22 @ 330pm
 Tanpin @ 11am to 10am
 02 days
 US Resing after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Workshops

Date/Time: 03.10.2022 16:07

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4944732

JC No: 905532112

Customer: COMFORT TRANSPORTATION PTE LTD
Customer No. 7010045
Address: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
Tel: (R) 65508755 (O)
(P)
Count Card No.


REGN NO: SH 8082T	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)03.10.2022 12:30	DATE/TIME IN
YR OF MANU. 07.10.2016	TARGET DATE
CHASSIS CODE JTDKB3FU803531055	COMPLETION DATE/TIME:

Incident Date: 03.10.2022
Incident Time: 3P 03.10.2022

JOB DESCRIPTION

/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SH 8082T** **CHIANG**

Vehicle No.: **SH 8082T**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard