

ASS. REC BY: Taufik

REF: INC NS/INC22012894/Tny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: MT/1203243-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Chery Vehicle: IN / OUT

Date / Time	Action / Instruction
	Taufikh confirmed lump sum : \$2450 and 3 days (red: \$2241.02, 48%)

Veh No: SHD4801M Yr Regn: 2019, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or _____

Make: Myundai Comiq C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 491014 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UMH4851CVLU 187400

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65R15

R: na

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/10/22

Survey held at Comfert Woying

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Robotop or Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

: Prel. Report
 : Final Report

1) 03/01/23

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
S + RS - SI	
Photos	

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Trivs (\$)

Report Format: 2450

Lump Sum / I.B.L. (%)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4801m
 MAKE 25.10.2019
 MODEL IONIQ G3

20.10.2022

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40 <i>de</i>
1	REAR BUMPER CENTRE MOULDING			\$451.25 <i>de</i>
1	REAR BUMPER REINFORCEMENT			\$394.80 <i>cur</i>
2	REAR BUMPER STAY LH/RH		\$138.10	\$276.20 <i>CHX</i>
10	REAR BUMPER CLIPS		\$2.20	\$22.00 <i>all</i>
1	REAR BUMPER LOWER CENTRE MOULDING			\$155.00 <i>xm</i>
1	REAR BUMPER UNDER CENTRE COVER			\$225.00 <i>xm</i>
1	REAR BUMPER SIDE UNDER COVER LH			\$108.00 <i>h</i>
1	BOOTLID H EMBLEM			\$38.00 <i>de</i>
1	BOOTLID EMBLEM IONID			\$31.80 <i>de</i>
1	BOOTLID EMBLEM HYBRID			\$24.30 <i>de</i>
1	REAR BUMPER TOW COVER			\$98.80 <i>all</i>
1	REAR BUMPER REFLECTOR LH			\$41.45 <i>set</i>
1	REAR BUMPER FOG LAMP			\$201.50 <i>xm</i>
2	REAR NUMBER PLATE LAMP		\$42.65	\$85.30 <i>xm</i>
2	REAR BUMPER BRACKET LH /RH		\$55.80	\$111.60 <i>de</i>
			1725.60	\$2,724.40
			1380.48	\$544.88
	DISCOUNTED TOTAL			\$2,179.52
1	BOOTLID COMFORT APP STICKER			\$40.00 <i>de</i>
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00 <i>de</i>
1	BOOTLID ADVERTISEMENT			\$100.00 <i>de</i>
1	REAR FENDER ADVERTISEMENT		\$100.00	\$200.00 <i>de</i>
1	REAR BUMPER MAT			\$50.00 <i>de</i>
1	REAR NUMBER PLATE W/HOLDER			\$55.00 <i>xm</i>
1	REAR REVERSE SENSOR			\$180.00 <i>nm</i>
				\$651.50
	Labour Charge			
	Panel Beating			\$1,050.00 <i>525</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Check wiring and lighting			\$60.00 <i>xm</i>
	Tuff Kote			\$90.00 <i>xm</i>
	Remove/Refix reverse sensor			\$60.00 <i>30</i>
			1055	\$1,860.00
	TOTAL LABOUR			
	ESTIMATE TOTAL		3037.48	\$4,691.02
			1150	
			2450	
			3 days #	

LKK Auto Consultants
 I hereby notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Tanfer 979 95449
input 20/10/14 30 pm
US rising after repair
Tanfer C lkkcamb.com
2-3 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.