

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO 201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
SINGAPORE 018961
TEL: 63958963
ATTN: Motor Claim Department \ ALLIANZ

Estimate No: EST1509094
Date: 21 Dec 2022
Policy No: GA623898/1
Veh Reg No: EN3232U
Make/Model: B.M.W. 318I LED NAV
SHAD. LIGHT
Chassis No: WBA8E36070NU81197
Engine No: F2681784B38B15A
Reg. Date: 16/11/2017

Your Ref No: TP 1222-7176
Claim Type: Third Party
Accident Date: 19/12/2022
TP Veh Reg No: SME6192J

Estimate Repair Cost to Vehicle No :EN3232U

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 TAIL LAMP - LH	654.8000	1 PC	654.80	
2 REAR BUMPER	1,300.550	1 PC	1,300.55	
3 REAR BUMPER SIDE HOLDER - LH/RH	155.8000	2 PC	311.60	
4 REAR BUMPER CLIPS	5.0000	10 PC	50.00	
			2,316.95	
		Less 5%	115.85	2,201.10
Labour				
5 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	400.0000	1 JOB	400.00	
6 TO RESPRAY PAINT ON ACCIDENT PORTIONS	500.0000	1 JOB	500.00	
7 TO CHECK WIRING	40.0000	1 JOB	40.00	
			940.00	940.00
Total				SS 3,141.10
Add GST @ 7%				219.88
Total Amount Payable				SS 3,360.98

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED SIXTY AND CENTS NINETY EIGHT ONLY

Not Authorized
du

P/P S

2 days

13/3/23

Wm ph. After repair

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: